

#### **Vehicle information**

Benz\_Sprinter Sprinter

VIN: WD2PD744X55718012

Mileage:

Diagnostic time: 2024-09-21 15:27:11

Diagnostic path: Manual selection\Sprinter\901.6; 902.6; 903.6; 904.6; 905.6(KWP 2000 - 2006)\USA,

Canada\OBDII\Auto scan\

#### Status report

System name	DTC counts	Status
CR-Common rail	02	Fault
EGS electronic transmission control	01	Fault
Transmission control	01	Fault
ESP-Electronic stability program	01	Fault
AB-Airbag	0	Pass
KI-Instrument cluster	0	Pass
WSP immobilizer	0	Pass
EWM-Electronic selector lever module	02	Fault
HZR-Heating control	01	Fault

#### 1. CR-Common rail---(02)

1.1 2009-1	The fill level sensor (water separator) does not supply a signal.	Stored&Current
1.2 2208-1	CAN bus: Brake signal .Plausibility	Stored

#### 2. EGS electronic transmission control---(01)

2.1 Event P2404	CAN fault - The signal of the stop light switch is implausible.	Stored	
-----------------	---	--------	--

#### 3. Transmission control---(01)

3.1 P2404 (2404)	Please refer to vehicle manual!	Stored
(2404)		

### 4. ESP-Electronic stability program---(01)



4.1 5159 adjustment Stored&Current	4.1 5159	Stop lamp switch, Short circuit to positive/ incorrect adjustment	Stored&Current
------------------------------------	----------	---	----------------

## 5. EWM-Electronic selector lever module---(02)

5.2 Event P1927	CAN fault - Signal 'Stop lamp switch' is implausible.	Stored
5.1 Event P1926	CAN communication is faulty.	Stored&Current

# 6. HZR-Heating control---(01)

6.1 B1005-007	Heater output has Short circuit to positive or Open circuit.	Stored&Current
---------------	--	----------------