



THE LASER

NEVER cut PVC, vinyl or Kydex.

They release hydrogen chloride, which becomes hydrochloric acid in your lungs and on the machine. It corrodes the optics and the rails for months afterwards, and it voids the warranty.

Unlabelled plastic? Do not cut it. Find out what it is first.

Fire

- 1 Stay with the laser. Never run it unattended — not for twelve minutes, not for two.
- 2 Cutting starts fires; engraving rarely does. Always use air assist when cutting through.
- 3 Clear the debris under the cutting grid. Most fires are lit by your job and fed by last month's scrap.
- 4 If a flame appears: press the EMERGENCY STOP, then get an instructor.

Two things people get wrong

- You cannot see the cutting beam. It is invisible infrared — the red dot is a separate pointer, and the glow is the material burning.
- The lid is not what protects you. Interlock switches cut the beam. Defeat them and you have a Class 4 laser in an open box.