

Visual Inspection Report - Sample Site

Observation 1: The Master Bedroom shows significant cracking on the east wall. This appears to be structural settling.

