

Thermal Analysis Report

Finding 1: Master Bedroom window shows significant thermal leakage (blue signatures).

Temperature differential of 5 degrees Celsius detected at the window seal.

Conclusion: Poor insulation and possible air infiltration.

