

ELECTRICAL PARTS

Description	Parts Charge	Service Charge
Non-Inverter IDU PCB repaired	1500.00	500.00
Non-Inverter ODU PCB repaired	2000.00	500.00
Inverter ODU PCB repaired	4000.00	750.00
Inverter IDU PCB repaired	2500.00	750.00
Non-Inverter IDU PCB replace	3000.00	750.00
Non-Inverter ODU PCB replace	3500.00	750.00
Inverter ODU PCB replace	4500.00	500.00
Inverter ODU PCB replace	7500.00	500.00
Replace LVT	1200.00	399.00
Sensor Replace	350.00	499.00
Contactor replaced	500.00	499.00
Contactor daikin O-General replaced	1500.00	499.00
Convert PCB With Remote	1500.00	499.00
Comp Capacitor - 2.5 to 60 mfd	400.00	349.00
Combo Capacitor Comp+Fan	500.00	499.00

Gas Charging

Description	Part Charge	Service charge
Gas R22 R32 R410 R134 R600	2500.00	499.00
Flair nut Replace	150.00	100.00
Cooling Coil / Condenser coil Repair	0.00	500.00
Copper Coil Condenser 1 ton	3500.00	499.00
Copper Coil Condenser 1.5 ton	4500.00	499.00
Copper Coil Condenser 2 ton	6000.00	499.00
Copper Cooling Coil 1 ton	4000.00	499.00
Copper Cooling Coil 1.5 ton	5000.00	499.00
Copper Cooling Coil 2 ton	5500.00	499.00
Capillary and filter	250.00	499.00
Compressor 0.8-1 ton	6500.00	499.00
Compressor 1.5 ton	7500.00	499.00
Compressor 2 ton	9500.00	499.00
Expansion valve	1200.00	499.00
dead nut	100.00	499.00
U band 1 pc	80.00	499.00
Copper Cooling Coil/condensor Coil	5000.00	0.00
Replacement Compressor (1 Ton)	4000.00	0.00
Replacement Compressor (1.5 Ton)	4500.00	0.00
Replacement Compressor (2 Ton)	5000.00	0.00
Service Valve replaced - 1/4	400.00	0.00
Service Valve replaced - 1/2	400.00	0.00
Service Valve replaced - 5/8	500.00	0.00
Copper Cooling Coil (split AC)-1	5500.00	0.00
Copper Cooling Coil (split AC)-1 Ton	5500.00	0.00
Copper Cooling Coil (split AC)-1.5 Ton	6500.00	0.00
Copper Cooling Coil (split AC)-2 Ton	7500.00	0.00

Copper Cooling Coil (split AC) O General & Mitsubishi - 1.5 Ton	7500.00	0.00
Copper Cooling Coil/condensor Coil (window AC) - 1 Ton	4500.00	0.00
Copper Cooling Coil/condensor Coil (window AC) - 1.5 Ton	5000.00	0.00
Copper Cooling Coil/condensor Coil (window AC) - 2 Ton	5500.00	0.00
Fuse Change in PCB	150.00	299.00
Cooling Coil repair with Anti-rust coating	899.00	0.00

Fan Motors

Description	Part Charge	Service charge
ODU Fan motor - Split AC	1800.00	499.00
Blower motor - split AC	2200.00	499.00
Blower replaced	1100.00	499.00
Replace Flap / Swing Motor	800.00	499.00
Motor Bearing Change	1000.00	0.00
Fan motor - Window AC	3000.00	499.00
Noise issue repair	0.00	499.00

Service & Installation

Description	Part Charge	Service charge
1 meter copper Pipe set (with insulation wire)	900.00	0.00
Split AC Wall stand	750.00	0.00
Outdoor unit reinstalled	799.00	0.00
Indoor unit reinstalled	699.00	0.00
Fastner complete set	200.00	0.00
Floor stand	550.00	0.00
Universal back plate	300.00	0.00
Lite AC Service	499.00	0.00
Foam-jet AC service	649.00	0.00
AC installation	1499.00	0.00
AC uninstallation	699.00	0.00
Anti-rust spray (avoid gas leak)	249.00	0.00
Drain Pipe replacement (1m)	100.00	0.00

Minor Repairs

Description	Part Charge	Service charge
Water Leakage Repaired-Split AC	350.00	499.00
Adjust Grill Locks	0.00	499.00
Adjust Pipe and tight compressor screw	0.00	499.00
Connector wires replaced (1m)	100.00	499.00
Tighten/Replace Thimble	50.00	499.00
External Dust/stick removal	0.00	499.00
Insulation refix	0.00	499.00

Drain pipe adjust	0.00	499.00
Noise adjustment in motor	0.00	499.00
Noise adjustment in blower	0.00	499.00
Noise adjustment in cabinet	0.00	499.00
Noise adjustment in swing flap	0.00	499.00
Water Leakage Repaired-Window AC	0.00	649.00

Other Parts

Description	Part Charge	Service charge
AC fan blade	700.00	499.00
Grill Cover	1500.00	499.00
Swing blade replaced	799.00	349.00
Universal remote	350.00	499.00
Water tray	1599.00	499.00
Stabilizer repair	1500.00	499.00
Sleeves (per piece)	50.00	0.00
Drain pipe adjust pr miter	100.00	499.00
Insulation refix	100.00	0.00
Noise issue repair	0.00	499.00
Stabilizer connection	0.00	499.00