


Prototype Testing/ Data Collection:

While testing our prototype, the primary data we gathered was that the arm weighed too much, which caused it to reset itself repeatedly. We also ran into issues with the handle being slightly warped

Images:



Tuesday Dec 3

Last meeting we had an engineer
come in and give us some feedback
one of his main critiques is the shortening
the design and rather than attach
it at the base of the arm instead
at the top of the cart.

Our first plan for today is cut down the
main center beams by 17 inches
my illustration for today is rather than
using webbing straps to attach it to
the base we use the metal straps with
holes in them. George and Garrett are
working on the notebook elements
in the process I also remove the pieces
with strap holes as they were
extra unneeded weight Current issue:
The frame can lift off from the
arm

Friday November 22

Section A was reworked and increased by about 4 weeks. Thank you George.

Garret began the Element B section of our project.

I finished the cutting but did not get a chance to test.

The main thing we need to do today is to test the arm on the cut and continue working on Element B.

We also learned that the Elements are not due till later on in the week so the priority of them has decreased.

The arm is still not short enough so we are removing half an inch from the base beam.

Had to remove half an inch from the width of the beam to fit in between the two slits. Beam 23 in by 2 1/2 in.

Thursday NOV 21

Team updates: we discussed team issues
we were having and then decided that instead
to fix them we need to do best
me → still working on prototype

geroge and garret are working on Elements
B and C while colt is working on
~~testing~~ cutting the front brace to length

~~our only possible~~ The main design
change we are making are cutting down
the length of the front base down by
half an inch

a possible improvement is ~~now~~ adding
another front base higher up to get two
contact points instead of just one

After cutting off the half inch it was
still slightly too long require another 1/4 of
an inch removed

