

Element J

Our external evaluators were not impressed by the state of our rose by the end of the project deadline. This was due to a variety of factors, including size, reusability, appearance, and various other minor factors. For starters, our rose design was too tall for the glass top, meaning we would have had to cut down on the height, leading to extra time being needed. Furthermore, they found our method of strings to be too difficult to reload for multiple uses, due to clotting in the tube and paperclips having trouble staying in their holes throughout loading. This clotting made it near impossible to load all the paperclips and, if fully loaded, meant pulling on one string would likely pull all, effectively dropping every rose, at once. With time, this problem could definitely have been fixed, however we tested the full design of the rose too late and were unable to resolve the issues. Mrs Moody also had issues with the appearance of the rose as it was not realistic enough for her standards. We tried to remedy this by playing with the different designs including the color and shape of the stem, size of the bud, as well as the size and number of the petals. Ultimately, we were unable to make any noticeable change to our design as she had already made her intentions of using a different company to build the rose.