

NV11, 1/2/4MX32 DDR, RGB, INTERNAL DVI-I, TV, AGP.

PCI DEVICE ID 0X0=0X112 FOR NV11.

STRAPS: AGP4X, SIDEBAND DIS, FAST WRITE ENA, ADP BIOS, NORMAL PCIAD, 14.318MHZ STRAP_RAM_TYPE [5:2]=1011-1MX32 DDR SDRAM

- 01. List of Schematic sheets
- 02. HOST INTERFACE NEW
- 03. FB(MEMORY)/NVXX DECOUPLING
- 04. NVXX BOOT STRAPS
- 05. DAC and MEDIA PORT
- 06. LOWER SDRAM FBI
- 07. BT & CH TV ENCODER
- 08. DFP/DVI/CLK_DVR
- 09. DC-DC CONVTR

HISTORY REV. :

- 1) Based on P39-A00
- 2) Schematic changes; role rev to B00
 - -remove BT device -strap resistor changes
 - -add/remove resistors and caps
 - -remove high dropout reg (u514)
- R502 changed from 20K to 10K

- Swapped LVDS signals back to "Rev A connections".
- Hi Freq. cap arrays Decoupled to GND:
 1) SMB_CLK

- 3) PID2_I2C_CLK (aka I2CSCL)
 4) PID3_I2C_DAT (aka I2CSDA)
- 5) PID3_I2CDAT (aka PID3)
- 6) PID2_I2CCLK (aka PID2) 7) PID1
- Added 10K, NO STUFF, from AGP_BUSY# to +3.3VSUS.
- Connected C279 to +5VSUS.

4) D00:



- 5) E00:
 - Implemented ECO change list "P41_D00_ECOs-X02.doc" in current working directory:
 - \nvcorp\applied\designs\working\nv11\XXX-P0041-0000-E00
 - Sync'd up netlist with Layout.
 - Connect the S0 input of the IMISM530 to 3.3VRUN instead of CLK_VDD
- - Added 1000pf cap (C535) in parallel to R535 for EMI supression.
- Changed mem termination from +3.3VRUN to +3.3VSUS. Affects R183-R186, C416
- 6a) E02-X01: Change C279 to no stuff per Dell request.
- 7) E03: Added SMD0603 foot print to the backside of board, C536 to DVI, DFP page.

















