## TABLE OF CONTENTS Description base on V263 1.0 NVIDIA P1310 A01 modify

P4, remove D3 64Mx16, change D3 128Mx8 [D0..D31]

P5, remove D3 64Mx16, change D3 128Mx8 [D32..D64]

P7, J4 change N31-2060061-H06 (2x6pin), cable change K10-1012002-V03 P8, J3 change N5B-30F0621-K06 (BLACK)

P10, remove BKT1 screw hole for DFM issue, add mark pad, J4x for single-end and diff pair trace.

P11, removed U501 infor rom, TP50x test pad Y1 change D04-1104600-F07

P12, change 2.0 pitch FAN conn.; remove fan control part

P13, removed 5V co-lay DIP part U2, PEX\_VDD U4 change I31-0010402-U33

P14, FBVDD U4 change I32-8120B02-R11, gate R52 0402 footprint change 0805, Q9 dual N MOS change D03-0150312-N03, remove co-lay 3V3 drv MOS

P15, NVVDD U1 change I32-8120B02-R11, gate R41 0402 footprint change 0805, remove GPIO7 parts, Q11Q12 MOS change D03-0903B4B-N03 L8 choke change

NVIDIA CORPORATION

600-11310-BASE-100

PCB REV



























