

OFFICIAL NORTH CAROLINA WOOD-DESTROYING INSECT INFORMATION REPORT

This is to report that a qualified inspector employed by the below-named firm has carefully inspected readily accessible areas of the property located at the address below for wood-destroying insects. This report specifically excludes hidden areas and areas not readily accessible (see section 2 below) and the undersigned pest control operator has not made any inspection of such hidden areas or of such areas not readily accessible. **This is not a warranty as to the total absence of wood-destroying insects or damage from same.** The inspection described herein was made on the basis of visible evidence. **This report is submitted without warranty, guarantee, or representation as to concealed evidence of infestation or damage or as to any future infestation.**

1.	
Seller's Name(s) <u>Heon & Sooja Lee</u>	
Buyer's Name(s) <u>Mahlian & Steve Carmichael</u>	
Address of Property <u>38 Forest Knoll Drive, Weaverville, NC, 28787</u>	
Structure(s) Inspected: A. Main Residence Only <u>---X---</u> B. Other _____	

FINDINGS

2. Areas of the property which are deemed to be obstructed or inaccessible:
living areas due to finished walls, floors, and ceilings; garage due to finished walls and ceiling; attics due to insulation; basement storage room due to finished ceiling; wood over slab flooring in basement; wood over slab step in garage; siding on slab

Note: Certain areas of all structures are obstructed or inaccessible (see numbers 2 & 3 on reverse side for conditions governing this report).

If there is evidence of a previous or an active infestation of subterranean termites and/or other wood-destroying insects **in the wooden members**; it must be assumed that there is some damage **to the wooden members** caused by this infestation, no matter how slight. If this is the case, the structural integrity of this property should be evaluated by a qualified building expert. (For the purpose of completing the report "infestation" means evidence of past or present activity by a wood-destroying insect visible in, on, or under a structure, or in or on debris under the structure.)

3. Inspection revealed visible evidence of:	Location of visible evidence of infestation:
☐ A. Subterranean termites ☐ 1. Control measure were performed. ☐ 2. No control measure were performed. ☐ 3. Visible evidence of a previously treated infestation, which now appears to be inactive.	
☒ B. Powder post Beetles ☐ 1. Control measure were performed. ☐ 2. No control measure were performed. ☒ 3. An infestation which now appears to be inactive	*Evidence to flooring (Characteristics of the Wood) - *See Page 2
☐ C. Old House Borers ☐ 1. Control measure were performed. ☐ 2. No control measure were performed. ☐ 3. An infestation which now appears to be inactive	
☒ D. Others <u>Carpenter Bees</u> ☐ 1. Control measure were performed. ☒ 2. No control measure were performed. ☐ 3. An infestation which now appears to be inactive	**Evidence to front deck hand rails - **See Page 2
☐ 4. No visible evidence of infestation from wood-destroying insects was observed.	
☒ 5. The following conditions conducive to subterranean termites were noted in this property: wood over slab flooring in basement; wood over slab step in garage; siding on slab; wood to ground hand rail posts, deck posts, steps, step stringers, underpinning, and underpinning framing	

FIRM: Biggs Pest ControlPCO Lic No. 1547PW Date 06/25/26Address: PO Box 6443, Hendersonville, NC 28793Telephone: () (828) 275-1014

Signature of Authorized Company Rep: _____


Title: Representative**Purchaser's signature is required on reverse side.****OVER**

CONDITIONS GOVERNING THIS REPORT

1. This report is based on observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and, in some cases, actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
2. This inspection and report are made on the basis of what was visible at the time of the inspection. An opinion is not given on areas that were enclosed or not readily accessible: finished areas of ground level rooms (basement and split level); areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes.
3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas are not considered to be readily accessible.
4. Detached garages, sheds, lean-tos, other buildings or fences on the property are not included in this inspection report unless specifically noted.
5. Neither I, nor the company for which I am acting, have had, presently have, or contemplate having any interest in this property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

REMARKS

This space should be used to clarify any statement made above.

This property was not inspected for the presence or absence of health-related molds or fungi. We are not qualified to and do not render an opinion concerning mold related air quality or any other health issues relating to this structure. Questions concerning the presence or absence of health-related molds or fungi or other health related issues, which may be associated with this property, should be addressed by a properly trained industrial Hygienist, Physician or the Public Health Official.

If there is evidence of a previous or an active infestation of Subterranean Termites and/or other wood-destroying insects in the wooden members, it must be assumed that there is some damage to the wooden members caused by this infestation, no matter how slight. If this is the case, the structural integrity of the property should be evaluated by a qualified building expert. (For the purpose of completing the report infestation means evidence of past or present activity by a wooddestroying insect visible in, or, or under a structure, and in or on debris under the structure.)

Void After 30 Days


***Powder Post Beetles: (Characteristics of the Wood) These are seasonal pests. Any inactive evidence found during our inspection may become active later, or other areas of activity may occur.**

****Carpenter Bees: See Attachments**


IT IS THE RESPONSIBILITY OF THE CLOSING AGENT TO OBTAIN PROPER SIGNATURES.

Purchaser's Signature(s) _____ Date Acknowledged _____

**Carpenter Bee
Hole**



**Carpenter
Bee
Frass**



Customer Name: **38 Forest Knoll Dr, Weaverville, NC 28787**
Date: **06/25/26**
Work Order #: **139812**



One Time Pest Service Agreement

Biggs Pest Control
PO Box 6443
Hendersonville, NC 28793
Licensee - Jeff Haney - 1547PW
Office - (828) 275-1014

Purchaser: Buyers Mahlian & Steve Carmichael Seller Heon & Sooja Lee

Telephone: _____

Telephone: _____

Email Address: _____

Mailing Address: _____ **City:** _____ **State:** _____ **Zip:** _____

Property Address: 38 Forest Knoll Drive **City:** Weaverville **State:** NC **Zip:** 28787

Property Description: Main Residence ONLY

Treatment Instructions: Liquid treatment by broadcast and/or injection treatment where active carpenter bee are noted on the front deck handrails to eliminate

Service Agreement

Biggs Pest Control agrees to provide pest control service by application of property control measures for the following pest(s):

Carpenter Bees

For this service, the customer promises to pay Biggs Pest Control the sum of \$275 payable when the service is performed. If additional service is necessary for the control of the above mentioned pest(s) within 180 days from the date of the initial service, such service shall be performed for \$0.00 per service visit.

Conditions (Read before signing)

- The foundation of Biggs Pest Control service is our commitment to quality pest control service and safety. Biggs Pest Control carefully uses of pesticides all of which are registered with the Environmental Protection Agency. All Customers are asked to always allow applications to dry thoroughly before family and pets return to the treated area(s). Individuals who are hypersensitive to any material are advised to avoid any unnecessary exposure to the pesticide(s).
- The customer agrees to make all areas of the structure readily available for each service. The customer will also comply with Biggs Pest Control's request to correct conditions contributing to, or causing, pest infestations (if any).
- The customer agrees to promptly render payment for each of the pest control services named above, to accept with no undue delay each of the regular pest control services, and to make all areas of the property readily available for each service. The customer will also comply with Biggs Pest Control's recommendations to correct conditions contributing to or causing mosquito infestations if applicable.
- Biggs Pest Control is not responsible for repair of, or compensation for present or future damage or injury or for any consequential or incidental damages done to the property its contents or any person by any insect pests or from the treatment or retreatments including but not limited to damages resulting from the sensitivity on the part of the customer or his/her family or guests to any materials or insects.
- Biggs Pest Control and The Customer agree that all claims and disputes arising out of or relating to this agreement shall be resolved by binding arbitration pursuant to the NC Uniform Arbitration Act.
- This agreement will be for an initial period of one year and shall continue thereafter until suspended by either party. Biggs Pest Control reserves the right to revise the charge of the service after the first year.

Customer Signature: _____

Date: _____

Representative: _____ Jeff Haney

Date: 06/25/26

Biggs Pest Control is locally family owned and operated!