Vality = 240V poles = 4

$$n = 1700 / min$$

 $F = 60 Hz$

$$N_{8} = 120 (60 Hz)$$


$$= 1800 rpm$$

$$S = N_{8} - N = 1800 - 1700$$

$$= 1800 - 1700$$


$$= 5.56\%$$

$$= 1800$$



Once the rotor begins to rotate the motor will begin to rotate with respect to the polarity of the windings.

In order to change the rotational direction we must change the direction of the windings.



Starting Motor. Apply voltage to rotor.
In order to change motor in the winding change the applied polarity in the windings.