| Addio Test Instrument | 5 |
|---|---|
| Ver 0.84 de W7PUA Z ==1030.000Hz Ref=50.00 | |
| Output Voltage Calibration | |
| 1-Connect Transmission path. | |
| 2-Terminate input with 50 Ohms. | |
| 3-Touch "Measure" below. | |
| Hint - Do this cal after Intput Voltage cal | |
| | |

Cancel

Measure

Cal

Done