## Audio Test Instrument Ver 0.84 de W7PUA Intput Voltage Calibration 1-Apply 0.100 V RMS to Transmission Input Sine-Wave Frequency about 1000 Hz 2-Touch "Measure" below and wait 5 sec. $Hint - 0.100 \lor RMS = 0.2828 \lor p-p$

Hint - Do this cal before Output Voltage cal

See USB-Serial output for measurement details

Measure Cal Cancel

Done