

Inspection Checklist

Exterior Envelope

CASE	SIR-2024-00091
INSPECTOR	Alex Reyes
INSPECTION DATE	November 5, 2024
CHECKLIST RESULT	47 of 52 line items satisfactory
FLAGGED ITEMS	5

Facade And Openings

- [FLAG] Level 2 spandrel panel crack documented for structural review.
- [FLAG] Southeast corner staining and efflorescence below window head documented for remediation scope.
- [PASS] Remaining window sealant lines show no visible perimeter failure.

Roof Edge And Drainage

- [FLAG] North parapet metal cap flashing lifted approximately 40mm with failed sealant.
- [PASS] Roof drainage outlets clear at time of inspection.

Ground Plane And Access

- [FLAG] Back entrance concrete threshold has 40-42mm height differential and requires interim marking.
- [PASS] No broad settlement or ponding observed at adjacent pavement.

Inspector Note

Recommend structural engineer review for the Level 2 crack and prompt envelope repairs before projected winter rain events.