

P.O. Box 51 Darlington, S.C. 29540 Phone: 843-393-2861 1111 Harry Byrd Hwy Darlington, S C. 29532 Fax: 843-395-5742

## **ARBITRATION DEPARTMENT FACSIMILE**

	Date:	-16-08
	Number of pages incli	uding cover sheet:
TO: Mark Ways	FROM:	H Bath
Phone #: 416-630-9297 Fax #: 416 -398-3332	Phone #:	
Fax #: <u>9/6 -398-3332</u>	Fax #:	843-395-5742
		9

Manheim Darlington

ιd

24733665548

d91:20 80 91 net

q84:20 80 81 nsl.

## **Manheim Post Sale Inspection Checklist**

14:39:33

				•			
Vehicle Information Custome			Customer Info	rmation		Notes	
·		•	WAYS AUTO SA	LES	Sale price: \$8,500		
	2000 ME ML430	RCEDIS	Contact:				
	GRAY		Гах: 416-398-		**CASH**		
	128,072 41GAB77	E1YA19772	Info: 9 Announcemiles over	- 100k to 2016			***************************************
Lights:		LI I A 1 7 / 12		C: dlr4::5005655; 2	2008-003-08 <b>-00</b> 66		
Opts:	ENG: 8CY	R: C TRN: A I	PS: X PB: X AC: Y EW: X	CES: X TOP SR CC	. X. EL. X. INT; L. CLR: GR	Y 4X4 A TL X SRS N	
Vehi	cle Insp	ection	POST SALE INSP	ECTION - FULL	COMPLETED	7-DAY GUARA	NTEE
QΚ	N/A	Concern	Check Points	C	Comment	·	
		8	NGINE (INCL DRIPPIN	IG OIL LEAK			
		т	RANSFER CASE (4WD	17 AWD)			
		<u> </u>	BS (ANTI-LOCK BRAI	KE SYSTEM)			
		E	MISSION CONTROL E	QUIPMENT		THE TOTAL MANAGEMENT AND ADDRESS OF THE PARTY	
		A	JC SYSTEM (CAUEND	ER YR OR NEW			
		W	/ARNING LIGHTS (INC	OL CYCLING)			
		0	DOMETER				
		s	RS (SUPP RESTRAINT	SYSTEM)	SRS Light Sad Batte	LON	
		T	RANSMISSION	_			·
		^	OCESSORIES (ELECTI	RICAL)	Sad Batte	Ry	
		р	AINTWORK 3 PNLS CU				
		F	LOOD DAMAGE				
		F	RAME/ UNIBODY DAI				, Lad
Arbit	ratable	Items For	ınd? 🛛 Yes 🗆 📈		CEERING HOSE LEAD		Abtel
Fram	e Check	<u>.</u>	(	EST 309.63 COMPLET	/ NEED TO REPAIR	<u> </u>	•
OK O	<b>)</b>	Concern	Comment	<u> </u>			
— <i>[/]</i> Gener	al Commo	ents:		Frame la	Ispection		
					arent Visible Damage	F (0)	. ,
				- rorspp.	age	Frame / Suge(ura) [.	amage (see below)
<b>D</b>						Ladder Frame	1 .
Kecon	ditioning	Recommen					Freca francisal
			Uni	Dody Structu <b>ral</b> F			Spring Pad
Reque	sted	Compl	cled	Önud a	C-Filter Restated		Akin stass number
	<del></del>	Inspecto	or: <u>LPO</u>	Panel/Firewall	F100**	, II 7	Transniewicz woode
Date:	1/16/200	08 Date:	1-15-08 Strut	Towar			frant side rail
Time:	9:31:17	Time:	A	oron .	1- N-	Swor acck Was	ll l
Seller :	Informati	on				- Rear	الأقوا
500565	5 HERL	ONG PONT	IAC CHEV BUICK IN	IC GO	B.= 0.	Red O	Figur authoristen com a merinater in transport in the community of the com
	)3-27 <b>5-2</b> 5		3-275-2562			PERMETER FRAME	Financia feature call
				Care	rt Rall Rocker Fanct		THAT HAVE TAIL
	Z:d		Z#Z99666#8	Sumort		Manheim Datingto ——ri	q94:20 80 81 m

03-92-0002

Service Writer: RKELLY

Service Tech:

VID:

Mileage:

Customer: 03-92-0002

Address:

City, State: Day Phone:

Night Phone:

Fax:

Estimate Ref: 3159 Date: January £5, 2008 Time: 05:02 PM

Vehicle:

2000 Mercedes Benz Truck ML 320 (163.154) V6-3.2L (112.942)

Description	Part #/Labor Ra	te Qty	Price/Time	Extended
Power Steering Line/Hose	- <b></b>			<b></b>
P/S Return Hose	1634600724	1	52.35	52.35
P/S Pressure Hose	1634602224	î	125.38	125.38
Power Steering Line/Hose		•	123.36	123.30
Replace				
Steering				
P/S Pressure & Return Hose (B)	Labor 50.00 / hr	1	2.30	115.00
Power steering fluid		2	5.00	10.00
Shop supplies		ĩ	6.90	
		•	0.50	6,90
		Labor Total		115.00
		Parts Total		187.73
		Non-Taxable	Total	6.90
			- 1 Otal	0.50
	i	Sub-Totai	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	309.63
		Total		\$ 309.63

Signature	Date