

## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

Overview	Client Address				
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road			
Description	Lifting Accessories/Two Leg Chain Sling	Stourbridge West Midlands DY9 7NG			
Type Of	6 Months				
Inspection		Report ID	54059	Page	1/1

Equipment Information					
Location	Tackle board bay 3	Inspected At			
I.S.I. Equipment Number	10233504	Stourbridge Turning & Grinding Holdings			
Date Of Manufacture		Rufford Road Stourbridge			
Serial Mark / Number	2512.4.1,9 ( 13 )	West Midlands			
SWL(s) For The Configuration Examined	4.25 ton @ 45 deg				

Inspection Report					
A - Defects Requiring Immediate Rectification:	None				
B - Defects Requiring rectification within a specified time period:	None				
C - Other defects:	1) The load hook safety catches are missing - to replace.				
D - Observations:	None				

## **General Comments**

Inspection carried out with minor defects

## **Declaration**

I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023



John Keber
Surveyor

Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village Amington Ema

Tamworth Staffordshire B77 4RP +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com