PWM Feed Through

Pressure Tracking Angle Tracking

Shared Data

i. e.: references, change state tasks $\,$

PWM Ref

User defined Ref Pattern/ Walking Mode