

ControlLogix Analog Servo Modules, Firmware Revision 16

Catalog Number 1756-HYD02, 1756-M02AE, 1756-M02AS

When to Use These Release Notes

Use these release notes for firmware revision 16.1.


Module	Catalog Number	Revision
ControlLogix 2-axis hydraulic servo module	1756-HYD02	16.1
ControlLogix 2-axis analog encoder servo module	1756-M02AE	16.1
ControlLogix 2-axis analog SSI servo module	1756-M02AS	16.1

Compatible Revisions

To use this revision, update your system as follows.

Update	To Revision
RSLinx software	2.51 or later
RSLogix 5000 software	16
ControlLogix controller	16

Before You Update Your Module



This disables the axes and makes updating the module easier.

Enhancements

These enhancements have been made in this revision.

Enhancement	Description
Loss of Feedback detection	With RSLogix 5000 version 16, the Loss-of-Feedback (LOF) detection has been enhanced for the 1756-M02AS and 1756-HYD02 modules to now recognize the LOF while the servo loop is off or disabled (MSF), as well as the prior check for LOF while the servo loop is on (MSO).

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444 Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640 Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846