3 Axis SERCOS interface™ Module Firmware v13.7 Release Note

Cat. No. 1756-M03SE

Introduction

This release note corresponds to the initial release (version 13.7) of the 3 Axis SERCOS interface™ Module. To use this firmware version, update your system as follows:

Update this software or firmware	Catalog Number:	Firmware/Software Version
Logix5550 Controller	1756-L1, -L1Mx	13
Logix5555 Controller	1756-L55Mx	13
Logix5563 Controller	1756-L63	13
RSLogix 5000™ Software	9324-RLD300ENE 9324-RLD600ENE 9324-RLD700NXENE	13

Restrictions

This revision contains the following restrictions:

ATTENTION

⚠

Each drive on the SERCOS ring must have a unique SERCOS address. If two axes have the same address on the same ring, both respond to commanded motion. This could lead to damage to the equipment or product and could result in personal injury.

For more information refer to our web site: www.ab.com/motion