




PARTS LIST		
ITEM	QTY	PART NUMBER
1	1	Passthrough Spindle
2	2	5111K594_Push-to-Connect Tube Fitting for Air and Water
3	1	Passthrough Base
4	1	9396K153 Silicone O-Ring
5	1	Passthrough Base Insert
6	1	90967A180_External Retaining Ring
8	1	9262K313_Oil-Resistant Buna-N O-Ring
9	1	Passthrough Spindle Plug
10	8	92010A326_Passivated 18-8 Stainless Steel Phillips Flat Head Screw
11	2	9262K159_Oil-Resistant Buna-N O-Ring

DRAWN Caleb Fangmeier	5/22/2024
CHECKED	
QA	
MFG	
APPROVED	

Boston University Physics			
TITLE Gantry Vacuum Passthrough Assembly			
SIZE A		DWG NO Passthrough Assembly	REV
SCALE 1 / 1.5		SHEET 1 OF 1	