
Fixing a Flash Location Misconfiguration for COMPSYS 704


Take the following steps to fix the bug

Step 1

- Look for the file system_stm32l4xx.c




- Change the `#if 0` on line 125 to `#if 1`



Step 2

- Look for the file STM32L476RGTX.ld



- Change `ORIGIN = 0x8000400,` on line 44 to `ORIGIN = 0x8000000,`

```
41 /* Specify the memory areas */
42 MEMORY
43 {
44 FLASH (rx)      : ORIGIN = 0x8000000, LENGTH = 496K
45 RAM (xrw)       : ORIGIN = 0x20000000, LENGTH = 96K
46 SRAM2 (xrw)     : ORIGIN = 0x10000000, LENGTH = 32K
47 }
48
```