




x1




x1




x2

1



x1


3




*Please be careful with inserts,
soldering irons can be dangerous



x1



2



x2

x1

4





x1



x1





x1



x1

4



x4



5





x1

6








x7


*Please be careful with inserts,
soldering irons can be dangerous

7





x1




x1

8



9

x2





x1



x3



x1

10

