Eisenhower Matrix

	Urgent	Not Urgent
Important	**DO** ● Wire TMP36 sensor. ● Read temperature in Serial Monitor. ● Connect motor with MOSFET and flyback diode. ● Implement automatic fan ON/OFF control.	**SCHEDULE** ● Temperature dependent speed factor ● Multiple Fans working synchronously ● Manual speed changer ● Add hysteresis.
Not Important	**DELEGATE** ● Use an LCD library. ● Use existing sensor libraries if useful. ● Use Python libraries for plotting data.	**DELETE** ● Build a custom temperature sensor. ● Design a motor driver from scratch. ● Build a mobile app or cloud dashboard for V1.0.