



PRE-PURCHASE TIMBER PEST

INSPECTION REPORT

Prepared in accordance with

AS 4349.3-2010 — Pre-Purchase Timber Pest

PROPERTY ADDRESS	7 Banksia Drive, Epping NSW 2121
CLIENT	Sam Taylor
INSPECTOR	Alex Example
PEST LICENCE NO.	NSW 000000
DATE OF INSPECTION	5 October 2026
INSPECTION TYPE	Pre-Purchase — Timber Pest
REPORT REFERENCE	KV-20261005-5008 · Version 1

RISK OF TERMITE ATTACK

HIGH

BASED ON

live termites · nest found · 2 conducive conditions · 3 areas not fully inspected

SUMMARY OF FINDINGS

LIVE TERMITES FOUND Gum tree in the backyard, about 15 m from the house	TERMITE DAMAGE OR OLD ACTIVITY FOUND Subfloor, rear bearer and the joist above it, under the back room
BORERS NONE SEEN	WOOD DECAY (ROT) NONE SEEN
BUILDER REFERRAL NONE FLAGGED	CONDUCTIVE CONDITIONS 2 FOUND elevated moisture; timber in contact with soil
RISK OF TERMITE ATTACK HIGH Based on live termites, nest found, 2 conducive conditions, 3 areas not fully inspected	TREATMENT RECOMMENDED YES Treat the active termites in the backyard tree; install a termite management system (chemical barrier or baiting system)

AREAS NOT FULLY INSPECTED

1.

The Interior: partly inspected
2.

Subfloor: partly inspected (No access to subfloor)
3.

Roof Void: partly inspected (Low clearance in roof void)

WHAT TO DO NEXT

1.

Termite treatment: Treat the active termites in the backyard tree; install a termite management system (chemical barrier or baiting system).
2.

Fix the conditions that attract termites: elevated moisture; timber in contact with soil.
3.

Provide access to interior, subfloor, roof void for a follow-up inspection.
4.

Next timber pest inspection: Next inspection in 3 months, then every 12 months.

This summary highlights the main results only. Read the full report, including the areas not inspected, the limitations and the terms, before relying on it.

1

CLIENT & JOB DETAILS

INSPECTING COMPANY	Example Pest Co
PEST CONTROL LICENCE	NSW 000000
COMPANY PHONE	0400 000 000
ABN	00 000 000 000
COMPANY EMAIL	office@example.com
PROPERTY INSPECTED	7 Banksia Drive, Epping NSW 2121
CLIENT NAME	Sam Taylor
INSPECTION DATE	5 October 2026
INSPECTION TYPE	Pre-Purchase — Timber Pest

2

PROPERTY DETAILS

STRUCTURE TYPE	Single storey house
WALL CONSTRUCTION	Double brick
FLOOR TYPE	Suspended timber floor
ROOF TYPE	Tiled roof, timber framed
ORIENTATION	North
OCCUPANCY STATUS	Occupied and furnished
WEATHER CONDITIONS	Fine and dry
YEAR / PERIOD OF CONSTRUCTION	1965-1985
APPLICABLE STANDARD	AS 4349.3-2010

Construction era indicates a HIGH likelihood of asbestos-containing materials (fibro/ACM sheeting). Noted as observation only — not disturbed. Recommend licensed asbestos assessor if suspected ACM identified.

3

UNDETECTED TIMBER PEST RISK ASSESSMENT

RISK OF UNDETECTED TIMBER PEST ACTIVITY

HIGH

Active or inactive termites found with uninspected areas. Further invasive inspection strongly recommended.

This rating reflects the risk of timber pest activity existing but not being detected at the time of inspection, due to access limitations. It is not an assessment of pest pressure or building susceptibility.

4

AREAS INSPECTED & OBSTRUCTIONS

THE INTERIOR	PARTLY INSPECTED
THE EXTERIOR	Inspected
SUBFLOOR	PARTLY INSPECTED — No access to subfloor
ROOF VOID	PARTLY INSPECTED — Low clearance in roof void
THE SITE	Inspected
FENCES	Inspected

WERE THERE OBSTRUCTIONS THAT MAY CONCEAL POSSIBLE TIMBER PEST ACTIVITY?

YES

HIGH RISK AREAS — ACCESS RECOMMENDED

Back section of the subfloor, not inspected because stored items block access

A further, more invasive inspection is strongly recommended of all obstructed areas once access is provided or obstructions are removed. It must be assumed that timber pest activity may exist in these areas.

5

RESTRICTIONS

WERE THERE CONDITIONS THAT RESTRICTED BUT DID NOT PREVENT INSPECTION?

NO

6

TIMBER PEST FINDINGS

TERMITE FINDING 1

LIVE TERMITES PRESENT

SPECIES / GENUS

Species not identified — further investigation required

TERMITE NEST FOUND?

YES

LOCATION OF ACTIVITY

Gum tree in the backyard, about 15 m from the house

DAMAGE / WORKINGS DESCRIPTION

Live termites in the tree; timbers around the base of the tree eaten out; possible nest in the tree

TERMITE FINDING 2

EVIDENCE ONLY — NO LIVE TERMITES

TERMITE NEST FOUND?

NOT RECORDED

LOCATION OF ACTIVITY

Subfloor, rear bearer and the joist above it, under the back room

DAMAGE / WORKINGS DESCRIPTION

Termite workings on the rear bearer and joist; no damage visible

BORERS & WOOD DECAY

BORERS OF SEASONED TIMBER

NONE

WOOD DECAY FUNGI (ROT)

NO

This inspection describes the location and visible extent of timber pest activity only. It does not assess structural damage severity — a licensed builder or structural engineer must be engaged for that purpose. Where live termites are found, concealed activity must be assumed in all areas not inspected.

7

CONDUCTIVE CONDITIONS

MOISTURE & DRAINAGE

WATER LEAKS	NO
MOISTURE DETECTED	YES
MOISTURE METER READING	28% — Back room
MOISTURE METER READING	15% — Bathroom
MOISTURE METER READING	14% — Kitchen

PHYSICAL BARRIERS & CONSTRUCTION

TIMBER-TO-SOIL CONTACT	YES
WEEP HOLES	CLEAR
AREAS OF CONCERN	Back section of the subfloor, not inspected because stored items block access

8

RECOMMENDATIONS

RISK OF TERMITE ATTACK	HIGH
TREATMENT RECOMMENDED	YES
TREATMENT TYPE	Treat the active termites in the backyard tree; install a termite management system (chemical barrier or baiting system)
RE-INSPECTION INTERVAL	Next inspection in 3 months, then every 12 months

Note: standard home and contents insurance policies in Australia typically do not cover damage caused by termites or other timber pests. Treatment and any resulting repairs are generally the responsibility of the property owner.

WHAT IS A TIMBER PEST INSPECTION?

A timber pest inspection is a visual, non-invasive inspection of a property for evidence of timber pest activity, damage, and conditions conducive to timber pest attack. The inspection is carried out by a qualified timber pest inspector in accordance with the applicable Australian Standard and is limited to those areas and sections of the property that are safely and reasonably accessible at the time of inspection.

What timber pests are covered?

This inspection covers subterranean termites (white ants), drywood termites, wood borers, and wood decay fungi (rot) where evidence is observable in accessible areas. These are the timber pests defined in AS 4349.3-2010.

What does "non-invasive" mean?

This inspection does not involve moving furniture, lifting floor coverings, cutting into walls, removing ceiling linings, dismantling built-in cabinetry, or any other action that could cause damage to the property or its contents. The inspector uses visual observation, a probe or screwdriver for tapping and sounding, and a moisture meter where appropriate. Splinter testing of structural timbers in the subfloor or roof void may be carried out where it can be done safely and with the property owner's consent.

What is "Reasonable Access"?

Reasonable access is defined in AS 4349.3-2010 as access to areas of the property that can be inspected without the need to remove, move, or dismantle any fixed or stored items, and which can be reached using a 3.6m ladder or less from the ground. Subfloor areas require a minimum clearance of 400mm under the lowest bearer, and roof voids require an access opening of at least 450mm x 400mm. Areas not meeting these criteria are outside the scope of this inspection.

What are "Readily Accessible Areas"?

Readily accessible areas are those parts of the property that can be reached and observed without the need to remove or disturb furniture, stored goods, floor coverings, wall or ceiling linings, insulation, or fixed cabinetry. The inspector is not required — and does not — move or displace any items during this inspection.

Does this inspection guarantee the property is free of termites?

No. A visual, non-invasive inspection of this type cannot detect timber pest activity or damage concealed within walls, under floors, inside structural timbers, or in any area that was not accessible at the time of inspection. Termites frequently operate within concealed spaces without external evidence. This report reflects the observable condition of the property at the specific date and time of inspection only. Regular professional re-inspections are the most effective ongoing protection available.

DEFINITIONS

Timber Pests:

Subterranean termites, drywood termites, borers of seasoned timber, and wood decay fungi (rot) as defined in AS 4349.3-2010.

Visual Inspection:

An inspection conducted by an inspector who uses their unaided visual faculties, and may use a probe, screwdriver, or moisture meter, to observe accessible areas of the property for evidence of timber pest activity, damage, and conducive conditions.

Reasonable Access:

Access to areas of a building that are safe, accessible, and do not require any removal, dismantling, or disturbance of fixed or stored items. Access is via a standard 3.6m ladder from ground level. Subfloor access requires minimum 400mm clearance; roof void access requires minimum 450mm x 400mm opening.

Readily Accessible Area:

An area that can be inspected without moving furniture, stored goods, floor coverings, wall or ceiling linings, insulation, or personal possessions.

Obstructions:

Physical items or conditions that prevent a complete visual inspection of an accessible area, including but not limited to furniture, stored goods, floor coverings, insulation, and vegetation. The inspector is not required to move obstructions.

Restrictions:

Physical, safety, or design constraints that prevent the inspector from entering an area under the applicable Australian Standard, including subfloor clearance below 400mm, access hatch dimensions below minimum standard, unsafe structures, asbestos risk, or height beyond safe ladder reach.

Conductive Conditions:

Conditions that may attract termites or provide conditions favourable to timber pest activity, including moisture, timber-to-soil contact, inadequate drainage, and conditions that compromise the integrity of an existing termite management system.

Active Termites:

Live termites sighted by the inspector during the inspection.

Inactive / Evidence Only:

Evidence of past termite activity including workings, mudding, damaged timber, and galleries, where no live termites were sighted. This finding is equally significant as active termites and warrants immediate professional attention.

IMPORTANT NOTICE

This inspection fee covers the cost of the inspection and report only. Treatment of any timber pest activity or damage identified, and any remedial work required, is not included in this fee and is the responsibility of the property owner. Standard home and contents insurance policies do not cover termite damage. If you have concerns about your coverage, contact your insurer directly.

TERMS & CONDITIONS OF INSPECTION

1. Purpose and Nature of This Inspection

This report records the findings of a visual, non-invasive timber pest inspection carried out in accordance with AS 4349.3-2010. The purpose is to identify observable evidence of timber pest activity, damage, and conditions conducive to pest attack within the accessible areas of the property at the time of inspection. This is not a structural inspection, a pest control treatment, a compliance audit, or a certificate of any kind, and it does not constitute a warranty or guarantee that the property is or will remain free of timber pests or associated damage.

2. Scope of Inspection

The inspection was confined to areas that were safely and reasonably accessible at the time of the inspection. Readily accessible areas are defined in AS 4349.3-2010 as those that can be inspected without moving furniture, lifting or removing floor coverings or wall linings, breaking apart building elements, exposing concealed spaces, or causing damage to the structure or its contents. The inspector did not move, displace, or remove any floor coverings, insulation, wall linings, ceiling materials, fixed cabinetry, furniture, stored items, or personal belongings. Subfloor and roof void areas were inspected only where safe and reasonable access was available and where minimum clearance dimensions prescribed in the relevant Standard were satisfied.

3. Areas Not Inspected — Obstructions and Restrictions

Certain areas of the property were not inspected due to physical obstructions, access restrictions, safety limitations, or structural design, as recorded in the body of this report. It is acknowledged that timber pest activity or damage may exist within any area that could not be inspected. Where high-risk areas have been identified or further investigation recommended, a follow-up inspection should be carried out once access is available. The absence of recorded findings in any area is not a representation that those areas are free of timber pest activity or damage.

4. Limitations of a Visual Non-Invasive Inspection

A visual, non-invasive inspection of the type described in AS 4349.3-2010 cannot detect activity or damage concealed within wall cavities, structural timber members, beneath floor slabs or coverings, inside hollow trees or stumps, behind fixed linings, or in any area that cannot be directly observed without causing damage. Subterranean termites are frequently active inside walls, flooring, and structural framing without any external indicators being visible. The findings of this report reflect observable conditions in accessible areas at the time of inspection only. No inspection of this nature can conclusively establish that a property is free of timber pest infestation, activity, or damage.

5. Damage Assessment — No Structural Opinion

Where timber pest damage has been recorded in this report, the description is limited to the observable location, affected building elements, and visible characteristics of the damage. The inspector is not qualified to assess the structural significance of any damage identified, and no opinion regarding structural integrity, load-bearing capacity, or engineering risk is expressed or implied in this report. Where a builder or engineer referral has been made, the client is strongly advised to engage a licensed builder or structural engineer to carry out a structural assessment before undertaking any remedial work or making decisions in reliance on that finding.

6. Conditions May Change After Inspection

The findings of this report reflect the observable condition of the property at the specific date and time of inspection. Timber pest colonies are dynamic and can expand, relocate, or establish new workings rapidly. Conditions at the property may change materially after the inspection date due to moisture fluctuations, building alterations, landscaping changes, or the natural movement of pest colonies. This

report does not warrant or predict the future condition of the property, and the client is advised that regular professional re-inspections are the most effective ongoing protection measure available.

7. Insurance

Standard home, contents, and building insurance policies in Australia do not generally cover loss or damage caused by termites, timber borers, or other timber pests. Timber pest damage is typically treated by Australian insurers as gradual deterioration rather than a sudden or accidental event and is excluded from most mainstream policies. The client is encouraged to obtain written confirmation from their insurer regarding the specific extent of their coverage before acting in reliance on this report.

8. Reliance on This Report — Client Use Only

This report has been prepared exclusively for the use of the client named on the cover page of this document. It must not be provided to, or relied upon by, any third party without the prior written consent of the inspecting company. Where this report has been sought in connection with a proposed property purchase, a formal Prior-to-Purchase Timber Pest Inspection prepared in accordance with AS 4349.3-2010 and obtained prior to exchange of contracts is strongly advised. The inspecting company and inspector accept no responsibility or liability to any party other than the named client for any loss, damage, or expense arising from reliance on the contents of this report.

9. Recommended Re-inspection Frequency

Annual timber pest inspections are the minimum recommended frequency under AS 3660.2-2017 in the absence of an installed termite management system. Where elevated risk factors are present — including proximity to bushland or trees, prior termite history at the property, high-moisture conditions in the subfloor or roof void, the presence of timber-to-soil contact, or susceptible construction materials — a six-monthly re-inspection interval is recommended. Where an existing termite management system is installed and verified, the re-inspection frequency specified by the system installer and manufacturer should be followed. Failure to maintain regular inspection intervals may affect the terms of any system warranty in place.

10. Applicable Standards and Legislation

This inspection and report have been prepared in accordance with AS 4349.3-2010 and the AEPMA (Australian Environmental Pest Managers Association) Code of Practice for Timber Pest Inspections where applicable. Where the property is newly constructed or has been subject to recent building work, the termite management provisions of the National Construction Code (NCC) and AS 3660.1-2014 (Termite Management — New Building Work) may also apply. State and Territory legislation may impose requirements additional to those set out in this Standard. This report is not a safety inspection, does not constitute advice regarding compliance with any building code or regulation, and is not a certificate of compliance under any legislation.

This report must be read in its entirety, including these Terms and Conditions, before any reliance is placed upon its contents.

10

INSPECTION AGREEMENT & ACKNOWLEDGEMENT

This report relates to the condition of the property in respect of timber pest activity at the time of inspection, limited to those areas that were reasonably accessible. It is not a warranty, guarantee, or certificate of compliance with any law, insurance policy, or building standard, and does not guarantee the property is, or will remain, free of termites or other timber pests. Conditions affecting the property may change after the inspection date, and concealed or inaccessible areas may contain damage or activity that could not be identified.

The client acknowledges the contents of this report and that the inspection has limitations. This report does not conclusively determine that the property is free of termites.

INSPECTOR DETAILS

Inspector Name: Alex Example

Pest Licence No.: NSW 000000

Inspector Signature: 

Date: 5 October 2026

PRE-INSPECTION AGREEMENT

Agreed by: Sam Taylor

Signed: 5 Oct 2026, 9:54 am, before the inspection

Client Signature: 

Generated by SAYON · 5 October 2026

Report ID: KV-20261005-5008 · Version 1 · AS 4349.3-2010 Compliant

Content fingerprint: F0B4-81AA-89B9-6433 · changes to the report change this code

PRE-INSPECTION AGREEMENT

1. The inspection

Example Pest Co will carry out a pre-purchase timber pest inspection of 7 Banksia Drive, Epping NSW 2121 for Sam Taylor on 5 October 2026, in line with AS 4349.3-2010.

2. What is inspected

A visual inspection of the readily accessible areas of the building and site for termites, borers of seasoned timber and wood decay fungi, and for conditions that make timber pest attack more likely. This normally covers the interior, roof space, subfloor, exterior, outbuildings, and the site within 50 m of the building, where they can be safely reached.

3. Limits of the inspection

The inspection is visual and non-invasive. We do not move furniture, stored goods, floor coverings, insulation or vegetation, and we do not cut, drill or remove any part of the building. Areas we cannot reach or see will be recorded in the report, and timber pests or damage may be hidden in them. The inspection cannot guarantee that the property is, or will stay, free of timber pests. It is not a building, structural, asbestos, mould or electrical inspection.

4. Invasive inspection

An invasive inspection is not included. If one is recommended, it needs a separate written agreement and fee.

5. Access

Please arrange safe access to all areas on the day. Any area we can't get into will be noted in the report, and coming back to inspect it later may cost extra.

6. The report

You will receive a written report after the inspection. It is for your use only and must not be relied on by anyone else without our written consent.

7. Fee

As quoted.

8. Special requests

None.

9. Your rights

Nothing in this agreement limits your rights under the Australian Consumer Law.

By signing, you confirm you have read and agree to this agreement before the inspection starts. You also agree to sign it electronically and to receive the report by email.

Agreed by: **Sam Taylor**

Signed: **5 Oct 2026, 9:54 am**

Signature: 