

Weld release sphere motion

NOT EXECUTED

Weld release was blocked by receiver construction failure.

No free-sphere motion, contact-force or net-wrench trace exists.