

What was repaired, and what was not

Production reset repaired; required simultaneous M/R/L and 4-ms validation remain incomplete.

Zero servo error was not equilibrium: initial $q_{acc} = 81.616851 \text{ rad/s}^2$ with $q_{vel} = 0$.

Natural settling retains nonzero target error and holding torque; q_{acc} falls to 0.001094 rad/s^2 .

Distal tendon split drift lasts tens of seconds; nominal contact geometry moves by up to 25 mm.

New settled sphere placement is collision-free, with minimum 0.4-mm clearance.

The frozen gentle ramp supplies valid sustained R/L data, not the required three-finger topology.

Common-state 4-ms startup compatibility is not solved. Gates and commands were not relaxed.

Next action requires PI review. P0.5R remains uncommitted; no merge to main.