

Foundational exit gate did not pass

Static audit; no contact, receiver, preload dynamics, or grasp-success criterion.

CASE A was required; observed classification is CASE C.

No equilibrium preload, direct test, local perturbation, or physics V1 freeze occurred.

Required next action: PI interpretation/model decision.

B03, fly-by, bounded-force receiver, B and RL remain gated.