SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	istockphoto-458080981-1024x1024.jpg
Session ID	a8b7f246-bce8-4952-b889-984bef185b99
Analysed	2026-03-03T12:01:30.977546+00:00
Total issues	8

Annotated Site Photo (box numbers match table rows)

Issues Found (8)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Several vertical and horizontal rebar sections are exposed and uncapped in the central area to the lower right, posing an impalement hazard.*	99%	x=0.72 y=0.57 w=0.20 h=0.33
2	**Other Issue** *More exposed and uncapped reinforcement bars are sticking up near the lower center-left, just above the wooden formwork area.*	98%	x=0.13 y=0.72 w=0.15 h=0.22
3	**Other Issue** *A cluster of vertical reinforcement bars is visible and uncapped at the upper left center of the image.*	97%	x=0.18 y=0.32 w=0.08 h=0.27
4	**Other Issue** *Loose timber, offcuts, and scattered construction debris cover the upper left area of the site.*	95%	x=0.07 y=0.18 w=0.29 h=0.20
5	**Other Issue** *Additional scattered pieces of rebar and construction material are present near the lower right below the crane structure.*	93%	x=0.53 y=0.79 w=0.15 h=0.17
6	**Other Issue** *A large cylindrical concrete bucket is left on its side near the center bottom, creating a trip hazard.*	93%	x=0.43 y=0.67 w=0.13 h=0.13
7	**Other Issue** *The formwork in the bottom left corner appears incomplete and has protruding joists and rough edges.*	92%	x=0.08 y=0.86 w=0.32 h=0.14
8	**Other Issue** *Numerous scattered boards, pipes, and construction debris are spread over the upper right quadrant of the site, indicating poor housekeeping.*	92%	x=0.74 y=0.05 w=0.24 h=0.21