


Login and validate work orders

Scan Employee Badge




041517863199 - Ernest Reed

Scan Manufacturing Order




WH/MO/DEMO1

Select Work Center




drill1 - Drill 1

Start Work Order




OBTPAUS

Pause Work Order




OBTPAUS

Mark As Done




OBTCLWO

Select Work Center



assembly1 - Assembly 1

Scan Manufacturing Order



WH/MO/DEMO1

Mark As Done



OBTCLWO

Scan Manufacturing Order



WH/MO/DEMO1


Close Production



OBTCLMO


Consume components and validate production

Scan Work Center




drill1 - Drill 1

Scan Manufacturing Order




WH/MO/DEMO2

Scan Product




601647855646 - Drawer Black - FURN_2100

Scan Lot Number




0000000010001

Scan Product




601647855647 - Drawer Case Black - FURN_5623

Scan Lot Number




0000000020045

Mark As Done



OBTCLWO

Select Work Center




assembly1 - Assembly 1

Scan Manufacturing Order



WH/MO/DEMO2

Mark As Done




OBTCLWO

Scan Manufacturing Order



WH/MO/DEMO2

Close Production



OBTCLMO