

## NORDSTROM RACK – TURNKEY PROTOTYPE

### SECTION 033536 – POLISHED CONCRETE FINISHING

---

- B. Make sequential passes with each pass perpendicular to previous pass using finer grit pad with each pass, up to 150 grit.
- C. Bring floor into desired flatness and smoothness using metal bonded diamond grinding equipment.
- D. Achieve maximum refinement with each pass until floor is scratch pattern free and before proceeding to finer grit pads.
- E. Hand-grind and polish as necessary to bring floor finish flush with walls and other vertical surfaces.
- F. Continue grinding until aggregate exposure matches approved field mock-ups.
- G. Fill pin holes with patching compound as recommended by the polishing system manufacturer.
- H. Remove dry dust or wet slurry prior to proceeding on to treatment stage.

#### 3.5 TREATING SURFACE IMPERFECTIONS

- A. Patching and Repair:
  - 1. Tint the Surface Patching and Repair Material, as directed by the manufacturer to match color of existing concrete substrate.
  - 2. Fill surface imperfections including, but not limited to, holes, surface damage, static cracks, air holes, pop-outs, and other voids.
  - 3. Work compound and treatment until color differences between concrete surface and filled surface imperfections are not reasonably noticeable when viewed from 10 feet away under lighting conditions similar to those present after construction.

#### 3.6 APPLICATION OF HARDENER/DENSIFIER

- A. Apply hardener/densifier to polished concrete slab in an overlapping motion to point of rejection in accordance with the system manufacturer's instructions.
- B. Remove excess material in a timely manner, in accordance with the system manufacturer's instructions, to prevent surface clouding or haze formation.
- C. Dispose of excess materials in a proper manner approved by the authority having jurisdiction (AHJ).

#### 3.7 HONING

- A. Use grinding equipment with resin bonded grinding pads.
- B. Grind concrete making as many sequential passes required to remove scratches, each pass perpendicular to previous pass, up to 400 grit pad reaching maximum refinement with each pass before proceeding to finer grit pads.
- C. Auto scrub or vacuum floor using squeegee vacuum attachment after each pass to remove dust, dirt and debris.

#### 3.8 POLISHING

- A. Use polishing equipment with resin bonded polishing and burnishing pads.
- B. Begin polishing in one direction starting with 800 grit pad.
- C. Make sequential passes with each pass perpendicular to previous pass.
- D. Auto scrub or vacuum floor using squeegee vacuum attachment after each pass.
- E. Continue polishing until gloss appearance matches approved field mock-ups.

#### 3.9 FINAL FINISHING AND SEALING

- A. Verify that the floor is dry and clear of debris prior to completion of the final polishing stages.