

MANAGEMENT REVIEW

Management without theatre.

OPERATIONS

SIX SIGMA AND VARIATION

Where Six Sigma came from, what 3.4 defects per million really means, Shewhart's two kinds of variation, whether Six Sigma pays, and a card for DMAIC.



3.4

defects per million opportunities is the Six Sigma level, a figure that already assumes the process drifts by 1.5 sigma.

MOTOROLA, 1986

INSIDE

COVER STORY

3.4 per million

PAGE 03

THE MODEL

Two kinds of variation

PAGE 05

TOOL OF THE ISSUE

The DMAIC card

PAGE 08

NO. 25 · OPERATIONS

In this issue

Every process varies: the same task takes eight minutes one day and twelve the next. This issue is about telling the variation that belongs to the process from the variation that has a cause you can find, and about Six Sigma, the programme built to reduce it.

Motorola dates Six Sigma to 1986. Its 3.4 defects per million opportunities assumes that a process drifts by 1.5 sigma over time. The idea behind it is older: in 1924 Walter Shewhart proposed the control chart to separate two sources of variation, and Deming estimated that 94% of troubles belong to the system. Two studies of 200 and 84 firms found that adopting Six Sigma went with better performance.

Stiven Janaqi EDITOR · STIVEN CATALYST

03 COVER STORY
3.4 per million

04 THE NUMBERS
From three to six sigma

05 THE MODEL
Two kinds of variation

06 WHAT THE RESEARCH SAYS
Does Six Sigma pay?

07 HOW IT IS MEASURED
Reading a control chart

08 TOOL OF THE ISSUE
The DMAIC card

09 SOURCES
Sources and method

HOW TO READ THIS ISSUE

Figure

Every figure has its source and year at the foot of its page.

Our reading

Where the editors interpret rather than the research, it says so.

Practice

The steps and the card are proposals to try, not research results.

COVER STORY

3.4 per million

Motorola dates the invention of Six Sigma to 1986. The term is credited to its engineer Bill Smith; chairman Bob Galvin launched the programme across the company in 1987.

Six Sigma sets out to reduce the variation of processes, because defects come from it. A process at six sigma gives 3.4 defects per million opportunities: not per million products, since one product can fail in many places.

3.4

defects per million opportunities, with the 1.5 sigma shift

≈0.002

per million at ±6 sigma without the shift

The 3.4 rests on a convention. Over time, the mean of a process is assumed to drift by up to 1.5 sigma, so a six-sigma process behaves in the long run like a 4.5-sigma one. The shift is Motorola's choice, not a law of statistics, and it has been criticised in the literature.

OUR READING

Six Sigma is less a number than a habit: measuring variation before arguing about it.

Sources: Motorola Solutions, 2026; iSixSigma, 2026

THE NUMBERS

From three to six sigma

With the 1.5 sigma convention, each step up the scale cuts the defects per million opportunities sharply.

DEFECTS PER MILLION OPPORTUNITIES, BY SIGMA LEVEL, WITH THE 1.5 SIGMA SHIFT

66,807

	6,210	233	3.4
3σ	4σ	5σ	6σ

93.32%

of opportunities without a defect at three sigma

99.99966%

at six sigma

OUR READING

The table is arithmetic on a convention, not measurements from factories. Its value is in showing how far apart three and six sigma are.

Source: iSixSigma, 2026

Calculated with the 1.5 sigma shift; some tables round three sigma to 66,810 or 66,800.

THE MODEL

Two kinds of variation

In an internal memo of 16 May 1924, Walter Shewhart of Western Electric proposed the control chart to his superiors. He separated two sources of variation.

Common causes

Part of the process itself

Reduced only by changing the process

Special causes

Appear now and then

Can be found and removed

94% of troubles and possibilities for improvement belong to the system, by Deming's estimate from experience; 6% are special.

OUR READING

Blaming a person for what the system produces changes nothing. Treating a special cause as normal lets it come back.

Sources: ASQ, Honorary Members, 2026; W. Edwards Deming, MIT Center for Advanced Engineering Study, 1986

Shewhart called them chance and assignable causes; Deming named them common and special. The 94% is Deming's estimate, not a measurement.

[More in the essay](#)

[A good SOP is not a document](#)

WHAT THE RESEARCH SAYS

Does Six Sigma pay?

Two studies in the Journal of Operations Management in 2012 compared firms that adopted Six Sigma with similar firms that did not.

01 200 firms

Morgan Swink and Brian Jacobs matched each firm with control firms of similar return on assets before adoption, industry and size. Six Sigma had a positive effect on return on assets, mainly through significant cuts in indirect costs.

02 84 firms, ten years

Scott Shafer and Sara Moeller followed firms from three years before adoption to six years after, against control groups. Overall, adopting Six Sigma went with better firm performance.

OUR READING

Both studies look at firms that announced adoption. They show what tended to follow, not what Six Sigma guarantees.

Sources: Morgan Swink & Brian W. Jacobs, Journal of Operations Management, 2012; Scott M. Shafer & Sara B. Moeller, Journal of Operations Management, 2012

Associations, not full proof of cause; we could not see the effect sizes of the second study.

HOW IT IS MEASURED

Reading a control chart

A control chart plots one measure over time, with limits three standard deviations from the mean. In a stable process a point falls outside them with a probability of 0.27%: about one false alarm in 370 points.

1

Plot one measure in time order

Per day, shift or batch, always counted the same way.

2

Draw the mean and the limits

Three standard deviations above and below the mean.

3

Act on signals

A point outside the limits points to a special cause: look for it.

4

Improve the process for the rest

Inside the limits, work on the process as a whole, not on single points.

HYPOTHETICAL EXAMPLE, MINUTES TO LOAD A TRUCK

Mean 42 minutes

Limits 30 to 54 minutes

Day 17 61 minutes: outside, a forklift was down

Only day 17 calls for a search for a cause; the rest is the process. The numbers are invented.

Source: NIST & SEMATECH, 2026

The steps and the example are the editors'; the limits and the false-alarm rate follow NIST.

Open the tool: Sigma & Control Chart

stivencatalyst.com/tools/sigma-control-chart/

TOOL OF THE ISSUE

The DMAIC card

DMAIC is ASQ's structured way to improve an existing process that falls short of its standard or of what the customer expects. One card per project.

01 Define the problem, the customer and the goal, on one page

02 Measure the baseline, and whether the measurement itself can be trusted

03 Analyze the main causes, shown with data

04 Improve the change, tested before it is rolled out

05 Control the control plan and the chart that keeps the gain

06 For a new process DMADV instead: define, measure, analyze, design, verify

Source: ASQ, 2026

The five phases follow ASQ; the card is the editors'.

Open the tool: [Six Sigma in the Warehouse](#)

stivencatalyst.com/tools/six-sigma-dmaic/

SOURCES AND METHOD

Every figure has a source.

The figures in this issue come from the sources below. The year shows how recent each one is.

Timeline

Motorola Solutions, 2026

https://www.motorolasolutions.com/en_xl/about/history/timeline.html

Sigma Performance Levels: One to Six Sigma

iSixSigma, 2026

<https://isixsigma.com/basics/sigma-performance-levels-one-six-sigma>

Walter A. Shewhart

ASQ, Honorary Members, 2026

<https://asq.org/about-asq/honorary-members/shewhart>

Out of the Crisis

W. Edwards Deming, MIT Center for Advanced Engineering Study, 1986

Six Sigma adoption: Operating performance impacts and contextual drivers of success

Morgan Swink & Brian W. Jacobs, Journal of Operations Management, 2012

<https://doi.org/10.1016/j.jom.2012.05.001>

The effects of Six Sigma on corporate performance: An empirical investigation

Scott M. Shafer & Sara B. Moeller, Journal of Operations Management, 2012

<https://doi.org/10.1016/j.jom.2012.10.002>

NIST/SEMATECH e-Handbook of Statistical Methods: Cusum Average Run Length

NIST & SEMATECH, 2026

<https://www.itl.nist.gov/div898/handbook/pmc/section3/pmc3231.htm>

DMAIC Process: Define, Measure, Analyze, Improve, Control

ASQ, 2026

<https://asq.org/quality-resources/dmaic>

EDITORIAL METHOD

Each figure was checked for its year, its publisher and what exactly it measures. Where the publisher's page could not be opened, the figure was checked against independent summaries and is marked “via”. The editors' interpretation is marked “Our reading”. Figures that could not be confirmed are not in the issue.



MANAGEMENT REVIEW

Management without theatre.

Every issue, one management question, checked against the best research.

ALL ISSUES

stivencatalyst.com/magazine/management-review.html