BOARD OF DIRECTORS

Gary Phillips '14

President: 14800 N SR 167 N Albany, IN 47320 (765) 789-8316 behere@netdirect.net

Steve King '14

Bill Conyers '15

Vice President: 50964 Lilac Rd, South Bend, IN (574) 277-8729 billconyerssr@yahoo.com

Ken Dettmer '15

15721 S 250W Columbus, IN 47201 (812) 342-4084

Dominick Andrisani '16

3608 Capilano Drive West Lafayette, IN 47906-8869 PH #(765)463-4975 andrisan@purdue.edu

Ted Stout '16

8525 W 700 S West Point, IN 47992-9258 PH# (765) 572-2467 stout8525@tds.net

James Johnston '17

Education Chairman: 806 Twyckingham Lane Kokomo, IN 46901-1885 (765) 452-8165 kokomoblacksmith@comcast.net

Keith Hicks '17

Secretary: 5184 State Road 252 Brookville, IN 47012 (765) 914-6584 keithhicks2011@gmail.com

Librarian: Larry Rosentrader 8715 E. 375 N Churubusco, IN 46723-9501 260-693-3267 rosentrad@cs.com

Editor: Bill Kendrick 1280 N 900 W Seymour, IN 47274 (812) 445-3009 bill.d.kendrick@cummins.com

Treasurer and membership secretary: Farrel Wells 8235 E 499 S Dunkirk, IN 47336-8807 PH # (765) 768-6235

THE FORGE FIRE

The Newsletter of the Indiana Blacksmithing Association, Inc.

An Affiliate Of The Artists-Blacksmiths' Association of North America, Inc.

IBA is a Not For Profit Indiana Corporation recognized by the IRS under section 501(c)(3)

10:00 AM is the regular meeting time for IBA Hammer-Ins with beginner training available at 9:00 AM.

PLEASE MAKE SURE TO ASK FOR HELP!

If you would like an IBA membership application form, please contact Farrel Wells, Membership Secretary (765) 768-6235.

BULK LOTS ARE AVAILABLE TO DEMONSTRATORS, SHOPS, SHOWS AND OTHERS WILLING TO MAKE THEM AVAILABLE. WE APPRECIATE YOUR HELP.

The Indiana Blacksmithing Association, Inc., its staff, officers, directors, members, and hosts and the *Forge Fire*, specifically disclaim any responsibility or liability for damages or injuries as a result of any construction, design, use, manufacture or other activity undertaken as a result of the use, or application of, information contained in any articles in the Forge Fire. The Indiana Blacksmithing Association, Inc. And the *Forge Fire* assumes no responsibility or liability for the accuracy, fitness, proper design, safety, or safe use of any information contained in the *Forge Fire*.

The Forge Fire is the newsletter of the Indiana Blacksmithing Association Inc. (IBA) IBA is an affiliate of the Artist-Blacksmiths Association of North America Inc. Permission is granted to other similar non-profit organizations to reproduce uncopyrighted articles originally appearing in The Forge Fire provided credit is given the original source.

More nearby resources and organizations for blacksmiths:

Rural Smiths of Mid-America:

Meetings are on the first Saturday of each month Call Moe Handy (317) 862-5647 for details.

IBA MEETING SCHEDULE

Check the latest *Forge Fire* for monthly **IBA** revisions.

Feb 15 2014	KEN DETTMER SHOP COLUMBUS
Mar 15 2014	IBA BUSINESS MEETING "DOC" RAMSEYER SHOP
Apr 19 2014	TBD
May 17 2014	TBD



INDEX

PG3 **IBA BALLOT**

PGS 5-7 SATELLITE **NEWS**

PG8 FORGE RAFFLE FOR 4-H

PG9 **DELLON BLANTON COL-**LECTION TO **KELLY FARM MUSEUM**

> PGS 10-11 **FORGE** WELDING

Dates to Remember

March 15 **IBA Business** Meeting

March 21-23 Little Giant Re**building Class** (see last months Forge Fire for details)

Editors Message

I want to open by congratulating Michael Wollowski and his wife on the birth of their son Tristan Michael Wollowski. Tristan was born on Sunday, January 19, 2014 at 2:30 pm. He weighed 8lbs 11oz and was 20 1/2" long. Mom and baby are doing fine, even though he decided to explore his new surroundings 2 weeks earlier than average and nine days earlier than scheduled.

I missed the January hammer in at Fall Creek. Sad to say but the chronic waves of winter storms and another one forecasted deterred me from the long drive. Gary Phillips did attend, and he reports they has a strong turn out with over 20 people present. Mark Thomas provided a good demonstration with assistance from his daughter. A number newer smiths received expert hands-on training.

This months hammer in will be at Ken Dettmer's shop in Columbus. I have not heard if there will be a special demonstrator or open forge. Either way I am sure will see some expert blacksmithing. This hammer in is always well attended with some very skilled blacksmiths on hand. Ken has a very spacious shop with some very fine tools. Be sure to come early and bring a chair.

In March we will have our annual business meeting. The meeting will be held at the Kelly Farm Museum, home of the "Doc" Ramseyer blacksmith Shop, south of Kokomo. One of the primary activities at the business meeting is to fill our board of directors positions. This year we have three announced candidates to fill two spots. Be sure to cast your ballot. My rough estimate is that only about 10% of our members vote, so every vote means a lot.

On page 9 you find an announcement from Jim Johnston that a large collection early American style ironwork created by Dellon Blanton has been donated to the Kelly Farm Museum. I am hopeful that some of that collection may be available for viewing at the business meeting.

The article on pages 10 and 11 came from a training manual for farm blacksmiths. The manual was published by the War Department in 1939.

Visit the IBA website at: www.indianablacksmithing.org

Ballot

IBA Board of Directors Vote for 2 Only

Ш	Steve King
	Gary Phillips
	Bill Newman
	Write in(Must be willing to serve)

Send ballot to:

Ken Dettmer 15721 S 250W Columbus, IN 47201

Mark the word 'Ballot' on envelope so it will not be opened until the business meeting in March.

Ballots may be cast at the business meeting.

Mailed ballots must be received by March 12th.

Ballot Ken Dettmer 15721 S 250W Columbus, IN 47201

> Ken Dettmer 15721 S 250W Columbus, IN 47201

IBA Satellite Groups and News

Sutton-Terock Memorial Blacksmith Shop

Meet: 2nd Saturday at 9 AM Contacts: Fred Oden (574) 223-3508 Dennis Todd (574) 542-4886

Wabash Valley Blacksmith Shop

Meet: 2nd Saturday at 9 AM

Contacts: Doug Moreland (217) 284-3457

Max Hoopengarner (812) 249-8303

Maumee Valley Blacksmiths

Meet: 2nd and 4th Saturday Contact: Clint Casey (260) 627-6270 John Schamber (260) 579-7303

Rocky Forge Blacksmith Guild

Meet: 2nd Saturday at 9 AM Contacts: Ted Stout (765) 572-2467

Whitewater Valley Blacksmiths

Meet: 2nd Saturday

Contact: Keith Hicks (765) 914-6584

Bunkum Valley Metalsmiths

Meet: 1st Saturday

Contacts: Doug Neukam (812) 259-4430 Steve Stoll (812) 486-9668 Kathy Malone (812) 725-3310

Jennings County Historical Society Blacksmith Shop

Meet: 2nd Saturday at 9 AM Contact: Ray Sease (812) 522-7722

Fall Creek Blacksmith Shop

Meet: 4th Saturday at 9 AM

Contacts: John Zile: (765) 533-4153 Larry Singer (765) 643-5953 Farrel Wells (765) 768-6235

St. Joe Valley Forgers

Meet: 4th Saturday at 9 AM

Contacts: Bill Convers (574) 277-8729 John Latowski (574) 344-1730

The Southern Indiana Meteorite Mashers

Contacts: Billy Merritt (812) 338-2876 Steve King (812) 797-0059 Jeff Reinhardt 812-949-7163

One Armed Blacksmith's Shop

Meet: 1st Saturday

Contact: Tim Metz (812) 447-2606

"Doc" Ramseyer Blacksmith Shop

Location: 6032W 550N, Sharpsville, IN 46060

Meet: 3rd Sunday at 2 PM Contacts: Mike Kelley

Charles Gruell (765) 513-5390

Jennings County Historical Society Blacksmith Shop

The January 11th meeting of The Jennings County Historical Society Blacksmiths was held at Paul and Judy Bray's home. The meeting lasted from 6:00am to 5:30pm. A fantastic breakfast and lunch was served by Paul and Judy as usual. Charlie Helton started the fire in the forge, then showed the proper way to make 2 different pairs of tongs which he later donated to the "Iron-in-the-Hat". Then Charlie instructed Tim Thompson on how to make chain links. Jack Newkam brought a "magic chain" that his grandfather had made for his wife when Jack was a little boy. No one in the group had ever seen anything close to what this chain looked like, (resembling chain mail). Harry Husby examined it very closely, and knowing Harry the way he is, had a working model made by dark! This was the first meeting of the year and the start of our 15th year as the Vernon Group. Many a great time has been had and a great future will be had by all. As usual, attendance was fantastic and a great "Iron-in the-Hat" was held. By Ray Sease

P.S. By Paul Bray Proper credit also needs to go to my two daughters, Natalie and Nicole, who were invaluable help with the meals. Thanks to all who came for making it a great success. Don't forget the State meeting at Kenny Dettmer's.

The February hammer in will be held at Bill Kendrick's shop at 1280N CR 900W (Jennings County). Bring a chair. Call 812-344-1021 if you need directions. Breakfast and lunch will be provided.

IBA Satellite Groups and News (continued)

Wabash Valley Blacksmith Shop

The Wabash Valley Blacksmith Shop held a gas forge work shop Saturday Jan. 25th at John Bennett's shop southeast of Rosedale In. The goal for the day was to build 6 single burner gas forges for club members. 11 members attended the workshop. Work stations were set up ahead of time and everyone had plenty of work to do.

As the day progressed John explained the hows and whys of each step involved in building the forges. Safety, design and troubleshooting were covered with discussions as well as hands on demonstrations. At the end of the day 6 fully functioning propane forges were completed, test fired and sent home with their new owners.

The day was one of the best group efforts I have had the pleasure of being a part of. I would like to thank all the participants for their hard work. I look forward to the next one in late Feb.

John Bennett Forge Master















IBA Satellite Groups and News (continued)

Bunkum Valley Metalsmiths

The Bunkum Valley Metalsmiths held their monthly meeting on January 4. We didn't have a meeting in December due to the weather, so it was like seeing long lost friends. We had several people at the meeting and some did a little blacksmithing. Seems like we did a lot of jawing at this one. I don't know why, but I didn't even get out to the forge to take any pics. I do know that Aaron, Vicky and Chris Baker were working on making some rams heads. I think that was mainly Vicky's project. Jerry Robinette and Steve Stoll hammered some on a sword Jerry is



making. We enjoyed lunch of Beaver stew, cooked soybeans, cornbread and a lot of other goodies brought in by everyone. I am sending a couple pictures of us doing what we do best, talk and eat. I would like to mention that one of our group has been missing, that is Carol Baker. She broke an arm and is in a rehab facility and we would appreciate thoughts an prayers for her. Until next time

Kathy Malone

The Southern Indiana Meteorite Mashers

This month's meeting was at Steve King's snug and warm shop in Paoli. Despite several inches of fresh snow, the shop was well filled. Dave Kunkler demonstrated a dragons head, and Jeff Reinhardt a wizard head bottle cap opener. Vicky Baker, Arron's wife came with the request to see animal heads and wizards demonstrated. She left having seen both, and having made her first wizard head on her own. The lunch of Steve's chili and soup beans from Jerry Robinette was well received. A lively Iron in the hat was held. Considering the weather it was an all around awesome way to spend a Saturday.

Next Meeting at Jason Hardin's shop on Mill creek road near Salem.

Medieval Faire Blacksmith

Doug and Mary Jo Smock own a medieval castle style Bed and Breakfast just West of Spencer Indiana (south of Poland) called Clayshire Castle (clayshirecastle.com). They are planning on having their first Medieval Faire this September 27th. They are looking for blacksmiths who would be interested in having a booth, doing a demonstration, etc. They will have entertainment and vendors with a Middle Ages theme.

They estimate between 1,000 and 2,000 attendees, based on prior open houses and similar new Renaissance Faires in Indiana, Illinois, and Ohio.

Anyone interested can contact Doug and Mary Jo at innkeeper@clayshirecastle.com, or call 317-797-3822.

Wabash Valley Blacksmiths Raffle Forge for 4-H

I am the forge master for the Wabash Valley Blacksmith Shop and I do a lot of work with the Parke County 4H blacksmith program. The program is starting it's 8th year this year. Last year we had 35 young smiths and 32 completed their projects. Through generous donations from local businesses and individuals we were able to erect a 32' x 48' blacksmith shop last spring. The shop has 4 single burner gas forges and 4 coal forges. The building is a work in progress and we are still finishing the lights and wiring.



The Wabash Valley Blacksmith Shop is raffling off a portable coal forge with all the proceeds going to the Parke County 4H blacksmith program.

John Vanada and I built the forge for the raffle. The table is 10 gauge mild steel and the firepot is fabricated from 1/4" plate. There is a tong rack on one end. The legs are 1" sch 40 black pipe and the forge breaks down for portability. I have attached several pictures of the Raffle forge and the new shop.

Tickets for the raffle are one dollar each or six for five dollars. Tickets are available through the Wabash Valley Blacksmith Shop and the Rocky Forge Blacksmith Guild.

The drawing will be held on 12 April 2014. You need not be present to win. The winner will be notified and arrangements made to deliver the forge.

Thank you in advance,

John Bennett









Dellon Blanton Collection to be Displayed at Kelly Farm Museum Submitted by Jim Johnston

On the 16th of November last year Charlie Gruell, Mike Kelly and myself met Dellon Blanton and Max Hoopengarner at the Kelly Farm Museum. In the past several years Dellon had reproduced the items in the Sauder collection of early American iron. In the interest of creating more space Dellon decided to donate the items to a museum where they could be seen and stay together. Dellon called me, I called Charlie, Charlie called Mike Kelly. Mike looked over the collection and was overwhelmed by it. He accepted the collection on behalf of the Museum. Hopefully It will be displayed soon. I saw the collection and was very impressed. Of course Dellon has impressed me many times over the years. Anyway the display will be well worth seeing, in fact you could see it at one of our satellite meetings. All would be welcome. The people in the photo are Mike Kelly, Charlie Gruell, myself and Max Hoopengarner. Of course the man of the hour, Dellon, took the photo so he is not included.

(Editors note the following is an excerpt from a 1939 government published manual)

BLACKSMITH PRACTICE

EM 862

War Department Education Manual

WELDING

309. The Welding Fire.-A good fire is the first requirement for welding. It is important for any blacksmithing work, but for welding it is indispensable.

The fire must be clean, that is, free from clinkers, brass, babbitt, etc., as such impurities tend to make the irons slippery instead of sticky at the welding temperature.

Lots of good coke is needed, as fresh coal not only makes a smoky fire but may also introduce some sulphur, which will make welding difficult, if not impossible.

The fire should be deep, with at least 4 in. of burning coke below the irons. There should also be burning coke on both sides and above the irons. Thus enough heat can be provided for thorough heating of the irons before the fire burns down.

The fire should be compact and well banked with dampened coal so as to confine. and concentrate the heat and to prevent too much air from going through the fire and causing the irons to oxidize or scale unduly. The fire should be thoroughly cleaned about every half hour while welding.

310. Scarfing the Irons.-Ends to be welded together should first be properly shaped or scarfed. Scarfed ends should be short, usually not over 1 1/2 times the thickness of the stock; and they should have rounded or convex surfaces, so that when they come together any slag or impurities will be squeezed out rather than trapped in the weld. Long, thin, tapering scarfs are to be avoided because they are easily burnt in the fire and because they cool and lose their welding heat very rapidly when removed from the fire, thus making welding exceedingly difficult.

In order to counteract the wasting away of the irons by scaling and the tendency to draw out from hammering when they are welded, the ends are commonly upset before scarfing. Scarfs on the ends of bars are made by working on the far edge of the anvil, striking backing-up or semi-upsetting blows with the toe of the hammer lower than the heel. (See Art. 314, page 235, for instructions on the link scarf.)

311. Welding Flux.-Borax or clean sand, or a mixture of the two, may be used as a welding flux. Commercial welding flux, however, such as may be bought from hardware stores, is usually more satisfactory; and since but a little is needed, it is probably best to buy a small package for the farm shop.

Flux is applied to the pieces to be welded after they are at a red or white heat and just before the welding heat is to be taken. It covers the irons and causes the oxide to melt at a lower temperature. The oxide must be melted before the irons can be welded.

Flux is not needed in welding wrought iron, as it may be heated above the melting temperature of the oxide without danger of burning. Although it is possible to weld mild steel without flux, it is much easier to do a good job with it. Tool steel cannot be welded without flux.

312. Heating the Irons.-The irons should be heated slowly at first, so they will heat thoroughly and uniformly throughout. The irons should be turned over once or twice during the heating to insure equal heating of all sides and parts.

After the irons reach a bright-red heat, remove them and dip the scarfed ends into flux, or sprinkle the flux on them with the fingers. Replace the irons in the fire and continue to heat, being careful not to brush the flux off the irons before it melts. Pull a few lumps of coke on top of the irons and raise the coke occasionally with the poker to see how the heating is progressing.

Care must be taken to see that both irons reach the welding heat at the same time. If one heats faster, pull it back into the edge of the fire for a few seconds. During the last part of the heating, have the scarfed sides of the irons down so they will be fully as hot as the other parts of the pieces.

313. The Welding Heat.-When the irons reach the welding temperature, they will be a brilliant, dazzling white; their surfaces will appear molten, much like a melting snowball; and a few explosive sparks will be given off. When the sparks start to come from the fire a little more violently, it is time to remove them and weld them together.

Points on Welding

- 1. Use a clean, deep, compact coke fire.
- 2. Clean the fire every half hour.
- 3. Make the scarfs short and thick, rather than long and thin. Scarfs should not be longer than 1 1/2 times the thickness of the stock.
- 4. Round the surfaces of scarfs so slag will be squeezed out rather than trapped in the weld.
- 5. Heat the irons to a good welding heat, yet do not burn them.
- 6. Bring both irons up to the welding heat at the same time.
- 7. Have the scarfed sides of the irons down in the fire just before removing them,
- 8. Before welding the irons together, shake off any slag or impurities by quickly rapping the tongs against the edge of the anvil.
- 9. Steadying the pieces over the edges of the anvil will help get them accurately and quickly placed.
- 10. Strike light or medium blows when irons are at the welding heat. Simply forcing the parts together is all that is necessary. Heavy blows mash the irons.
- 11. Work fast; keep the hammer on the anvil within easy reach.
- 12. In case of failure to stick, do not continue hammering. Reflux and try again, being sure the fire is in good shape, and that you heat the irons hot enough.

Note: If you are interested in learning to forge weld, Nathan Allen will be instructing a forge welding class at Conner Prairie on March 22. For registration please call Conner Prairie Guest Services dept. at 317-776-6000.



Address Correction Requested If Undeliverable return to sender With original address legible

Kenny Dettmer's Shop

February 15

15721 S 250W Columbus, IN

From the North: take I 65 S to Ogilvillel / Walesboro (exit 64) turn. right. Go to the 1st cross-roads (300 W). Turn left. Approx 1 mile to the "T" . Turn left (600s). Go to 250W. Approx. 4 miles to a brick house on your left.

From the South: I 65N to Jonesville exit 55 turn. right, go to road 950 (in Jonesville). Turn left. Go to 250W turn. right. Kenny's house is approx 1/2 mile on your right.

Please bring a dish to share.

Kelley Farms (Doc Ramseyer), Business Meeting

March 15

6032 W 550 N Sharpsville, IN 46060

Located just west of US-31. Approximately 6 miles north of SR-28 (Tipton) or 3 miles south of SR-26 (Kokomo).

Please bring a dish to share

First Class Mail