Requirements for Sev

A typical target (deployed) SEV machine

We need to collect some information on a typical target machine to carry out the subsequent steps. On a typical such machine:

1. Make sure SEV is enabled and the machine is "registered."
2. Get the ARK Certificate for this family of machines. If the machine is registered, the ARK certificate should be in the following ***file-location***.
3. Obtain machine information by running the utility, **utility name**. Save this information for later steps.

The machine that builds the VM

1. The certifier framework as built by the scripts
2. At a minimum, a vmlinuz; ideally, a script to build the desired VM with the desired packages. The vmlinuz should have the sev device driver.
3. At a minimum, a built initrd.img containing cf_utility.exe, cf_key_server.exe and cf_key_server.exe together with the libraries they depend on. Ideally, there should be an automatic build corresponding to vmlinuz naming the Linux machine policy file (e.g.- firewall rules, module loading, passwords,…) and other files to be included in initrd.img. Initram.img must also have the policy key certificate for every security domain the VM will participate in.
4. Directories for running the VM under the Certifier.
5. Nice to have: A deployment script for setting up the images on the host machine from some standard package.

On machine that measures VM (often the Certifier Server)

1. A copy of the IBM measurement tool
2. The correct ovmf (firmware) file and its file location on this machine.
3. A copy of the VM elements:
    a. vmlinuz
    b. initrd.img
4. The correct arguments for target machine to be certified:
    a. cpu type

b. number of vcpus
c. cpu model
d. cpu stepping
e. cpu family
f. cpu features
g. vmm-type
h. The command line for launching the VM.

On Certifier Server (for policy building)

1. The Certifier repository
2. The ARK Cert for the families to be certified
3. For each VM measurement to be certified
    a. The SEV features to be checked in validating an attestation
    b. The output of the measurement tool (usually hex) for the VM to be certified

On each target VM

1. SEV must be enabled
2. The location of the files containing the ARK, ASK and VCEK must be supplied to the certifier installation scripts.
3. The appropriate firmware (OVMF file).