

Legend
• Fade = PWM LED pulse
• Solid = LED on
• LCD line 1 = date/time
• LCD line 2 alternates: temp / state+SP

Set Point Buttons (no state change)

- Red (GPIO 25): +1°F
- Blue (GPIO 12): -1°F

UART Output (every 30s): state,currentTempF,setPoint