Ok 1st Part Checklist Category	Reaction Plan
Safety Standard Operation is present and applied (including PPEs use)	**Stop work or do not start work.** Any safety risks identified need to be immediately escalated by Andon light and notify Team Lead. If proper PPE is not worn, operator must immediately obtain and wear the required PPE.
Safety Machine (status, alarms) with AM (auto maintenance) performed	**Stop work.** Perform any necessary Autonmous Maintenance immediately.
5S at station is acceptable	Notify Team Lead. Clean the station per 5S standards. Create DISS action to address gaps.
Red/Yellow Box Available and identified and empty	Notify Team Lead. Remove Red Tag items from the bin and place in appropriate area. Create DISS action to address gaps.
Correct standard Work Instruction available	**Stop work.** Immediately notify the Manufacturing Engineer to provide the document or fix LDS to display the work instruction.
Components available and identified	Raise Andon light for material shortage. Create DISS action to have JBS or OWS updated.
Controle Fixtures / intruments available and calibrated	**Stop work.** Immediately notify Team Lead of which instrument is out of date. Create DISS action to have Methods address the item.
Golden & Dummies samples (red rabbits) available and calibrated	**Stop work.** Immediately notify Team Lead if Golden Unit and Red Rabbit are not available. Create DISS action to have Methods/Quality address the missing Golden Unit/Red Rabbit.
Poka Yoke / Jidoka available and validated	**Stop work.** Immediately raise Andon light for Methods/Test Automation to address the issue.