Rotations of motor per minute 6pm) = 200 No. of teeth on driver gear = 25 No. of teeth on driven gear = 40 : According to wondition, Speed of driver gear = No. of teeth ondriver gear x opm

No. of teeth on driven gear

= 25 x 2005 speed of driver gear = 125 rpm



