

ENGINEER ASSESSMENT REPORT

Representative Audatex-style assessment using manufacturer times

Assessment Number	EA-0001	Created	02/08/2026
Claim Reference	CLM-UK-001	Date of Incident	21/07/2026
Policy Number	POL-UK-2026001	Authorisation Status	Authorised
Registration	CG01 UKX	VIN	TMAJ3813DMJ10001
Manufacturer	HYUNDAI	Model	KONA HYBRID
Variant	ADVANCE 129 AUTO	Odometer	12,875

VEHICLE CONDITION

Pre-Accident Condition: Good

Severity of Impact: Light

Vehicle Status on Inspection: Unroadworthy

Damage Areas: Front bumper, radiator grille, front radar sensor

REPAIR INFORMATION

Category	Code	Description	Qty/Hrs	Rate	Total
Labour	865246R77	Front bumper remove and refit	1	£78.50	£78.50
Labour	865246R77AX	Radiator grille remove and refit	0.3	£78.50	£23.55
Labour	991088A00	Radar sensor calibrate	0.3	£78.50	£23.55
Paint	0281	Front bumper repair paint plastic	1	£94.20	£94.20
Extra	RECOVERY	Standard vehicle recovery	1	£150.00	£150.00

CALCULATION

Labour Rate: £78.50

Paint Rate: £78.50

Total Labour: £125.60

Total Paint/Material Costs: £94.20

Total Parts: £0.00

Total Additional Costs: £150.00

Grand Total Excl VAT: £369.80

VAT Rate: 20%

VAT: £73.96

Grand Total Incl VAT: £443.76

ENGINEER ASSESSMENT REPORT — SOURCE EVIDENCE

Assessment Number: EA-0001

This page preserves the inspection context used alongside the priced operations. No price is inferred from an image or diagram.

INSPECTION CONTEXT	DAMAGE SUMMARY
Vehicle photographed during engineer inspection Pre-accident condition: Good Inspection status: Unroadworthy	Front bumper Radiator grille Front radar sensor

AUDIT NOTE

The structured operation rows on the preceding page remain the governed source for engineer quantities, rates and totals. This supporting page is retained for traceability only.