

Test Summary

ScriptName	Model3 Seat EOL.seq
SerialNumber	TFR20181000FRT
PartNumber	1456942-00-С
Model	M3_L
Status	Error
StartDateTime	2020-06-29 07:26:40.190
ExecTime	99sec
SoftwareVersion	3.0.12.173
Station	HDW-MFG-1RS-03
station_alias	Model3 LH #1
Socket	0
Operator	teslamotors

Model3 Seat EOL.seq	Error
Initialize Hardware	Error
Close Hardware	Error

Script/Test/Measurement	Report Text	Tag	Date & Time	Status
Model3 Seat EOL.seq			2020-06-29 07:26:43.176	Error
Initialize Hardware	Error Code: -1950679035 Error Message: Open Variable Connection in host.lvlibp:crio_cmdVariable.vi->host.lvlibp:crio_set_do.vi- >host.lvlibp:crio_set_do.vi.ProxyCaller LabVIEW: (Hex 0x8BBB0005) Unable to locate the shared variable in the Shared Variable Engine (SVE). Deployment of this shared variable may have failed, the SVE has not started, or the SVE is too busy to respond to this request.		2020-06-29 07:26:43.199	Error
Turn ON Relay	Error Code: -1950679035 Error Message: Open Variable Connection in host.lvlibp:crio_cmdVariable.vi->host.lvlibp:crio_set_do.vi- >host.lvlibp:crio_set_do.vi.ProxyCaller LabVIEW: (Hex 0x8BBB0005) Unable to locate the shared variable in the Shared Variable Engine (SVE). Deployment of this shared variable may have failed, the SVE has not started, or the SVE is too busy to respond to this request.		2020-06-29 07:26:43.231	Error
Close Hardware	Error Code: -1950679035 Error Message: Open Variable Connection in host.lvlibp:crio_cmdVariable.vi->host.lvlibp:crio_set_do.vi- >host.lvlibp:crio_set_do.vi.ProxyCaller LabVIEW: (Hex 0x8BBB0005) Unable to locate the shared variable in the Shared Variable Engine (SVE). Deployment of this shared variable may have failed, the SVE has not started, or the SVE is too busy to respond to this request.		2020-06-29 07:26:46.884	Error
Turn OFF Relay	Error Code: -1950679035 Error Message: Open Variable Connection in host.lvlibp:crio_cmdVariable.vi->host.lvlibp:crio_set_do.vi- >host.lvlibp:crio_set_do.vi.ProxyCaller LabVIEW: (Hex Ox8BBB0005) Unable to locate the shared variable in the Shared Variable Engine (SVE). Deployment of this shared variable may have failed, the SVE has not started, or the SVE is too busy to respond to this request.		2020-06-29 07:26:47.045	Error