




NOTES:

1. ALL DIMENSIONS IN MILLIMETERS, UNLESS OTHERWISE NOTED.
2. BEFORE MAKING EXOTHERMIC WELD CONNECTIONS, REMOVE ALL DIRT, RUST OR OTHER FOREIGN MATERIAL.
3. COMPLETED EXOTHERMIC WELD CONNECTIONS SHALL BE SEALED WITH A LAYER OF APPROVED BITUMEN TO PREVENT INGRESS OF MOISTURE.
4. EACH H-PILE SHALL ALSO BE BONDED TO NEAREST PILE CAP STARTER BAR VIA COPPER CABLE.

INSTALLATION OF H-PILE EARTHING

NTS

STANDARD DETAIL

16448

JACOBS