

- -ACN Terminal to corner bottom right +check sze of snubber component -Region for fuse , thermal absorb
- Open air for acl
- tear drop
- label
- should removr 3 resistor serial & CT small?
- Rechack relay pin on ACL line , change footprint
- co ve chan acl cua header 8x2 chua dung









