DATASET 1: Industrial Knowledge Record Equipment: Pump P-101 Location: Plant Section 1 Date: 2024-01-12 Maintenance Record: - Issue: Vibration detected - Action: Bearing replaced - Technician: Rajesh Kumar - Downtime: 3 hours Inspection Report: - Temperature: 71 C - Pressure: 6 bar - Status: Needs monitoring Safety Note: - Follow lockout-tagout procedure before maintenance Root Cause Analysis: - Likely cause: Bearing wear due to lubrication failure

DATASET 2: Industrial Knowledge Record Equipment: Pump P-102 Location: Plant Section 2 Date: 2024-02-12 Maintenance Record: - Issue: Vibration detected - Action: Bearing replaced - Technician: Rajesh Kumar - Downtime: 4 hours Inspection Report: - Temperature: 72 C - Pressure: 7 bar - Status: Needs monitoring Safety Note: - Follow lockout-tagout procedure before maintenance Root Cause Analysis: - Likely cause: Bearing wear due to lubrication failure

DATASET 3: Industrial Knowledge Record Equipment: Pump P-103 Location: Plant Section 3 Date: 2024-03-12 Maintenance Record: - Issue: Vibration detected - Action: Bearing replaced - Technician: Rajesh Kumar - Downtime: 5 hours Inspection Report: - Temperature: 73 C - Pressure: 8 bar - Status: Needs monitoring Safety Note: - Follow lockout-tagout procedure before maintenance Root Cause Analysis: - Likely cause: Bearing wear due to lubrication failure

DATASET 4: Industrial Knowledge Record Equipment: Pump P-104 Location: Plant Section 4 Date: 2024-04-12 Maintenance Record: - Issue: Vibration detected - Action: Bearing replaced - Technician: Rajesh Kumar - Downtime: 6 hours Inspection Report: - Temperature: 74 C - Pressure: 9 bar - Status: Needs monitoring Safety Note: - Follow lockout-tagout procedure before maintenance Root Cause Analysis: - Likely cause: Bearing wear due to lubrication failure

DATASET 5: Industrial Knowledge Record Equipment: Pump P-105 Location: Plant Section 5 Date: 2024-05-12 Maintenance Record: - Issue: Vibration detected - Action: Bearing replaced - Technician: Rajesh Kumar - Downtime: 7 hours Inspection Report: - Temperature: 75 C - Pressure: 10 bar - Status: Needs monitoring Safety Note: - Follow lockout-tagout procedure before maintenance Root Cause Analysis: - Likely cause: Bearing wear due to lubrication failure