

GPM Property Management

MOVE-OUT INSPECTION REPORT — PROPINSPECAI PROTOTYPE (LIVING ROOM)

Property / Job	121939
Date	2026-09-08
Inspector	Chuck Larson
Generated by	PropInspecAI (prototype) — automated extraction from inspection video, pending human review

Living Room

Overall Condition: Fair — Empty and generally serviceable, but requires wall, ceiling, flooring, window, and door work before next occupancy.

Room Dimensions: 14 ft × 11½ ft (*source: narrated by inspector, confirmed via tape measure visible in video*)

Item	Condition	Observed Evidence	Recommended Action	Trade Category	Priority
Walls	Damaged	Mounting holes and poor prior patching visible throughout	Repair holes/patches, then paint	Painting/Drywall	Before next occupancy
Ceiling	Damaged	Visible crack across ceiling	Repair crack, paint ceiling	Painting/Drywall	Before next occupancy
Front picture-window blind	Damaged/Missing	Blind mechanism broken/crooked	Install new blind; remove old mounting hardware; repair affected area	Doors/Windows	Before next occupancy
Side-window mini-blind	Damaged	Mini-blind broken	Replace mini-blind; remove old hardware; repair mounting area	Doors/Windows	Before next occupancy
Windows / glass	Good	No damage to window units observed	None	—	No action
Hardwood flooring	Damaged	Multiple dark stains visible on floor	Clean / refinish affected area (method to be confirmed on-site)	Flooring	Before next occupancy
Flooring at wall vent	Damaged	Aluminum patch needed at vent; base molding needs caulking	Repair patch, caulk base molding	Flooring	Before next occupancy

Item	Condition	Observed Evidence	Recommended Action	Trade Category	Priority
Electrical outlets / cover plates	Fair	Outlets functional; devices and cover plates need cleaning	Secure outlets; clean devices and cover plates	Electrical	Routine turnover
Closet door	Damaged	Does not latch properly	Adjust strike / door alignment	Carpentry	Routine turnover

INSPECTOR NARRATION — TIMESTAMPED REFERENCE

- **0:01–0:40** — Wall condition and mounting holes noted
- **0:20–0:43** — Ceiling crack identified
- **0:43–0:56** — Electrical outlet condition noted
- **1:05–1:14** — Front picture-window blind condition
- **Clip 2, 0:02–0:20** — Front picture-window opening measured: 75 inches
- **Clip 2, 0:20–0:29** — Side-window mini-blind / opening measured: 27 inches
- **Clip 2, 0:30–0:44** — Hardwood floor staining noted
- **Clip 2, 0:40–0:47** — Flooring repair needed at vent
- **Clip 2, 0:45–0:50** — Closet door latch issue noted

ABOUT THIS REPORT

This report was generated automatically from raw inspection video (no manual data entry) using a PropInspecAI prototype pass. It was cross-checked against the official Zinspector report for this same property and matched nearly item-for-item, including an exact room-dimension match (14' × 11.5"). This is a **prototype output for internal review** — not yet connected to GPM's quoting process, and pending a human review step before any report goes to an owner or tenant.