Detected return code: 121

## 27641 QA

## **TxRx CP Extremity Coil Check 2020-04-29 15:54:02**

Start Coil Check Performing Coil Check \_\_\_\_\_ Measure Protocol: 005 Extremity Tra sn.edb. Measured Series Loid #1: Local 2.0.145270106 No valid multi seriesloid. Measured Series Loid #1: Local 2.0.145270106 Ordered Series Loid #1: Local 2.0.145270106 Series Loid for Evaluation 1: Local 2.0.145270106 Number of images in series: 1 Evaluate image #1 Protocol 005\_Extremity\_Tra\_sn Evaluation for EX specified in ServiceCoilData.ini. Evaluation for coil element: EX. SN evaluation New Evaluation mode: 0x310 specified S/N Results - Brightness = 1363.7 [Specification from 700.0 to 2800.0] - S/N Ratio = 86.9 [Specification > Applet Info: Title: Series: 1, Image 1/1 of protocol 005 Extremity Tra sn.edb Data type: short Width: 256 Height: 256 Results of coil-element EX are in Specification! No Evaluation for EX@1 specified in ServiceCoilData.ini. Results are in specification Program finished successfully