27641 QA

Spine Matrix Coil Check 2020-05-04 13:38:45

```
Detected return code: 121


Start Coil Check
-----------------------
Performing Coil Check
-----------------------
Measure Protocol: 005_SpineMatrix_SP1_SP2_Tra_sn.edb.
Measured Series Loid #1:
Local 2.0.145865959
Measured Series Loid #2:
Local 2.0.145848460
Ordered Series Loid #1:
Local 2.0.145865959
Series Loid for Evaluation 1:
Local 2.0.145865959
Number of images in series: 2
Evaluate image #1
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
No Evaluation for SP1_SP2 specified in ServiceCoilData.ini.
No Evaluation for SP1_SP2@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
No Evaluation for SP1_SP2 specified in ServiceCoilData.ini.
No Evaluation for SP1_SP2@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145848460
Series Loid for Evaluation 2:
Local 2.0.145848460
Number of images in series: 4
Evaluate image #1
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
Slice shift: 70.000000 (specified), 70.000000 (image)
Evaluation for SP1 specified in ServiceCoilData.ini.
Evaluation for coil element: SP1.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness              =   479.7 [Specification from  300.0 to 1200.0]
- S/N Ratio               =    35.1 [Specification >    33.0]
Applet Info:
Title:  Series: 2, Image 1/4 of protocol 005_SpineMatrix_SP1_SP2_Tra_sn.edb
Data type:      short
Width: 256
Height: 256

Results of coil-element SP1 are in Specification!
Slice shift: 70.000000 (specified), 70.000000 (image)
No Evaluation for SP1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
```

```
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP2 specified in ServiceCoilData.ini.
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP1 specified in ServiceCoilData.ini.
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP1@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005_SpineMatrix_SP1_SP2_Tra_sn
Slice shift: -70.000000 (specified), -70.000000 (image)
Evaluation for SP2 specified in ServiceCoilData.ini.
Evaluation for coil element: SP2.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness               =  514.1 [Specification from    0.0 to    0.0]
- S/N Ratio                =   38.0 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 4/4 of protocol 005_SpineMatrix_SP1_SP2_Tra_sn.edb
Data type:      short
Width:  256
Height: 256

Results of coil-element SP2 are in Specification!
Slice shift: -70.000000 (specified), -70.000000 (image)
No Evaluation for SP2@1 specified in ServiceCoilData.ini.
Detected return code: 122


Start Coil Check
-----------------------
Performing Coil Check
-----------------------
Measure Protocol: 005_SpineMatrix_SP3_SP4_Tra_sn.edb.
Measured Series Loid #1:
Local 2.0.145869037
Measured Series Loid #2:
Local 2.0.145851534
Ordered Series Loid #1:
Local 2.0.145869037
Series Loid for Evaluation 1:
Local 2.0.145869037
Number of images in series: 2
Evaluate image #1
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
No Evaluation for SP3_SP4 specified in ServiceCoilData.ini.
No Evaluation for SP3_SP4@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
No Evaluation for SP3_SP4 specified in ServiceCoilData.ini.
No Evaluation for SP3_SP4@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145851534
Series Loid for Evaluation 2:
Local 2.0.145851534
Number of images in series: 4
```

```
Evaluate image #1
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
Slice shift: 70.000000 (specified), 70.000000 (image)
Evaluation for SP3 specified in ServiceCoilData.ini.
Evaluation for coil element: SP3.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness               =  498.1 [Specification from    0.0 to    0.0]
- S/N Ratio                =   35.4 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 1/4 of protocol 005_SpineMatrix_SP3_SP4_Tra_sn.edb
Data type:      short
Width:  256
Height: 256

Results of coil-element SP3 are in Specification!
Slice shift: 70.000000 (specified), 70.000000 (image)
No Evaluation for SP3@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP4 specified in ServiceCoilData.ini.
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP4@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP3 specified in ServiceCoilData.ini.
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005_SpineMatrix_SP3_SP4_Tra_sn
Slice shift: -70.000000 (specified), -70.000000 (image)
Evaluation for SP4 specified in ServiceCoilData.ini.
Evaluation for coil element: SP4.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness               =  531.5 [Specification from    0.0 to    0.0]
- S/N Ratio                =   38.6 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 4/4 of protocol 005_SpineMatrix_SP3_SP4_Tra_sn.edb
Data type:      short
Width:  256
Height: 256

Results of coil-element SP4 are in Specification!
Slice shift: -70.000000 (specified), -70.000000 (image)
No Evaluation for SP4@1 specified in ServiceCoilData.ini.
Detected return code: 123


Start Coil Check
-----------------------
Performing Coil Check
-----------------------
Measure Protocol: 005_SpineMatrix_SP5_SP6_Tra_sn.edb.
Measured Series Loid #1:
```

```
Local 2.0.145871089
Measured Series Loid #2:
Local 2.0.145854608
Ordered Series Loid #1:
Local 2.0.145871089
Series Loid for Evaluation 1:
Local 2.0.145871089
Number of images in series: 2
Evaluate image #1
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
No Evaluation for SP5_SP6 specified in ServiceCoilData.ini.
No Evaluation for SP5_SP6@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
No Evaluation for SP5_SP6 specified in ServiceCoilData.ini.
No Evaluation for SP5_SP6@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145854608
Series Loid for Evaluation 2:
Local 2.0.145854608
Number of images in series: 4
Evaluate image #1
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
Slice shift: 70.000000 (specified), 70.000000 (image)
Evaluation for SP5 specified in ServiceCoilData.ini.
Evaluation for coil element: SP5.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness                   =  512.1 [Specification from    0.0 to    0.0]
- S/N Ratio                    =   35.0 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 1/4 of protocol 005_SpineMatrix_SP5_SP6_Tra_sn.edb
Data type:      short
Width:  256
Height: 256

Results of coil-element SP5 are in Specification!
Slice shift: 70.000000 (specified), 70.000000 (image)
No Evaluation for SP5@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP6 specified in ServiceCoilData.ini.
Slice shift: -70.000000 (specified), 70.000000 (image)
No Evaluation for SP6@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP5 specified in ServiceCoilData.ini.
Slice shift: 70.000000 (specified), -70.000000 (image)
No Evaluation for SP5@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005_SpineMatrix_SP5_SP6_Tra_sn
Slice shift: -70.000000 (specified), -70.000000 (image)
Evaluation for SP6 specified in ServiceCoilData.ini.
Evaluation for coil element: SP6.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
```

```
- Brightness                  =   528.7 [Specification from    0.0 to    0.0]
- S/N Ratio                   =    36.3 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 4/4 of protocol 005_SpineMatrix_SP5_SP6_Tra_sn.edb
Data type:      short
Width:  256
Height: 256


Results of coil-element SP6 are in Specification!
Slice shift: -70.000000 (specified), -70.000000 (image)
No Evaluation for SP6@1 specified in ServiceCoilData.ini.
Detected return code: 124



Start Coil Check
-----------------------
Performing Coil Check
-----------------------
Measure Protocol: 005_SpineMatrix_SP7_SP8_Tra_sn.edb.
Measured Series Loid #1:
Local 2.0.145873141
Measured Series Loid #2:
Local 2.0.145867934
Ordered Series Loid #1:
Local 2.0.145873141
Series Loid for Evaluation 1:
Local 2.0.145873141
Number of images in series: 2
Evaluate image #1
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
No Evaluation for SP7_SP8 specified in ServiceCoilData.ini.
No Evaluation for SP7_SP8@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
No Evaluation for SP7_SP8 specified in ServiceCoilData.ini.
No Evaluation for SP7_SP8@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145867934
Series Loid for Evaluation 2:
Local 2.0.145867934
Number of images in series: 4
Evaluate image #1
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
Slice shift: 2.000000 (specified), -120.000000 (image)
No Evaluation for SP7 specified in ServiceCoilData.ini.
Slice shift: 2.000000 (specified), -120.000000 (image)
No Evaluation for SP7@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
Slice shift: -120.000000 (specified), -120.000000 (image)
Evaluation for SP8 specified in ServiceCoilData.ini.
Evaluation for coil element: SP8.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness                  =   529.7 [Specification from    0.0 to    0.0]
- S/N Ratio                   =    39.1 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 2/4 of protocol 005_SpineMatrix_SP7_SP8_Tra_sn.edb
```

```
Data type:      short
Width:  256
Height: 256

Results of coil-element SP8 are in Specification!
Slice shift: -120.000000 (specified), -120.000000 (image)
No Evaluation for SP8@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
Slice shift: 2.000000 (specified), 2.000000 (image)
Evaluation for SP7 specified in ServiceCoilData.ini.
Evaluation for coil element: SP7.
SN evaluation
New Evaluation mode: 0x916 specified
S/N Results
- Brightness                    =  559.0 [Specification from    0.0 to    0.0]
- S/N Ratio                     =   37.3 [Specification >   33.0]
Applet Info:
Title:  Series: 2, Image 3/4 of protocol 005_SpineMatrix_SP7_SP8_Tra_sn.edb
Data type:      short
Width:  256
Height: 256

Results of coil-element SP7 are in Specification!
Slice shift: 2.000000 (specified), 2.000000 (image)
No Evaluation for SP7@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005_SpineMatrix_SP7_SP8_Tra_sn
Slice shift: -120.000000 (specified), 2.000000 (image)
No Evaluation for SP8 specified in ServiceCoilData.ini.
Slice shift: -120.000000 (specified), 2.000000 (image)
No Evaluation for SP8@1 specified in ServiceCoilData.ini.
Results are in specification
Program finished succesfully
```