

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 463556 更换后 PCCB 制动片

信息

更换后 PCCB 制动片的相关信息

步骤与灰铸铁制动系统相同。 → **463856** 更换后盘式制动器制动片

981120, 981121, 981130, 981131, 981320, 981321, 981330, 981331, 981140, 981141, 981340, 981341

年款 起始时间 2012

C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C46, C96, C97, C98, C99

