

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 463456 更换前 PCCB 制动片

更换前 PCCB 制动片

更换前 PCCB 制动片



信息

更换 PCCB 制动片的步骤与更换灰铸铁制动器上的制动片的步骤相同。

1. 更换前盘式制动器制动片。 → 463656 *更换前盘式制动器制动片*

982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351

年款 起始时间 2017

C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C45, C46, C96, C97, C98, C99

baochi123D

baochimingcheservice@gmail.com

Aug 23, 2019

