Ch. 5 Notes: For 5.20 Assume Ku = 5.0 (It's not given)

Problem 5.8

From setting time equation on p80: $t_s = 4\tau = \frac{4}{\zeta \omega_n}$

For this problem, $t_s = 4$ seconds

From equations on p97: $\zeta = \cos(\theta) = \frac{|\sigma|}{|\omega_n|}$

Substituting: $t_s = \frac{4}{|\sigma|} = 4$ seconds

The condition to be met on the s-plane:

- $|\sigma| = 1$
- Since our system does settle out to reach 98% of its final value in 4 seconds, it is stable. Since the system is stable, σ is a negative value $\sigma = -1$

Problem 5.9

From table or equation on p80-81: 5% O.S. $\rightarrow \xi = 0.7$

From settle time equation on p80: $t_s = 4 \sec onds = 4\tau = \frac{4}{\xi \omega_n}$

$$\therefore \xi \omega_n = \frac{4}{4} = 1 \Longrightarrow \omega_n = \frac{1}{0.7} = 1.43$$

CL TF
$$\frac{C(s)}{R(s)} = \frac{\frac{K}{s(s+p)}}{1 + \frac{K}{s(s+p)}} = \frac{K}{s^2 + sp + K} = \frac{\omega_n^2}{s^2 + 2s\xi\omega_n + \omega_n^2}$$

Set like terms equal

$$p = 2\xi\omega_n = 2*0.7*1.43 = 2$$

$$K = \omega_n^2 = 1.43^2 = 2$$

Problem 5.13

Plant model transfer function is on p273


$$G(s) = \frac{5}{s^2 + 7s + 10} = \frac{5}{(s+2)(s+5)}$$

poles at -2, -5


asymptote break away at $\frac{-2-5}{2} = -3.5$

asymptotes at $\pm 180^{\circ}$

To find K you can use matlab "sys = TF(num,den)" and then "rltool(sys)" and click points to find K. (In this case K = 59.3 where damping is 0.2)



Or you can find K by hand as shown below



$$\cos(\xi) = \theta$$

$$\cos(0.2) = \theta \Rightarrow \theta = 78.46^{\circ}$$

CL TF
$$\frac{C(s)}{R(s)} = \frac{\frac{5K}{s^2 + 7s + 10}}{1 + \frac{5K}{s^2 + 7s + 10}} = \frac{5K}{s^2 + 7s + 10 + 5K} = \frac{\omega_n^2}{s^2 + 2s\xi\omega_n + \omega_n^2}$$

$$2\xi\omega_n=7$$

$$\omega_n^2 = 10 + 5K$$

$$\xi = 0.2$$

$$\omega_n = hypotinuse = 17.50$$


OY

$$\omega_n = \frac{7}{2*0.2} = 17.50$$

$$\therefore 17.50^2 = 10 + 5K \Rightarrow K = 59.25$$

Problem 5.14

For proportional controller with Kp = 2



CL TF
$$\frac{C(s)}{R(s)} = \frac{\frac{5K_p}{s+5}}{1 + \frac{5K_p}{s+5}} = \frac{5K_p}{s+5+5K_p} = \frac{5*2}{s+5+5*2} = \frac{10}{s+15}$$

Let $s \rightarrow 0$

$$C_{SS} = 2 * \frac{10}{15} = \frac{4}{3}$$

$$e_{SS} = R_{SS} - C_{SS} = 2 - \frac{4}{3} = \frac{2}{3}$$

For proportional-integral controller with Kp = 2 and Ti = 1

From p234
$$G_C = K_p \left(1 + \frac{1}{T_i s} + T_d s \right) = 2 + \frac{2}{s}$$

CL TF
$$\frac{C(s)}{R(s)} = \frac{\frac{5(2+\frac{2}{s})}{s+5}}{\frac{5(2+\frac{2}{s})}{s+5}} = \frac{10+\frac{2}{s}}{s+5+10+\frac{2}{s}} = \frac{10s+2}{s^2+15s+2}$$

Let
$$s \rightarrow 0$$

$$C_{SS} = 2 * \frac{2}{2} = 2$$

$$e_{SS} = R_{SS} - C_{SS} = 2 - 2 = 0$$

Problem 5.19

From p235 Figure 46

$$D \approx 0.125$$

$$T \approx 0.75 - 0.125 = 0.625$$

$$K_p = 1.2 \frac{T}{D} = 1.2 \frac{0.625}{0.125} = 6$$

$$T_i = 2D = 2 * 0.125 = 0.25$$

$$T_d = 0.5D = 0.5 * 0.125 = 0.0625$$

From p234
$$G_C = K_p \left(1 + \frac{1}{T_i s} + T_d s \right) = 6 \left(1 + \frac{1}{0.25 s} + 0.0625 s \right) = K_p + \frac{K_i}{s} + K_d s$$

$$K_{p} = 6$$

$$K_i = 6/0.25 = 24$$

$$K_d = 6*0.0625 = 0.375$$

Problem 5.20

P236 fig 47 and table 2

$$T_u = 0.42$$
 (estimate)

$$K_u=20$$

$$K_P = 0.6K_u = (0.6*20) = 12$$

$$T_i = 0.5T_u = 0.21$$

$$T_d = 0.125 T_u = 0.0525$$

$$K_i = K_p \! / T_i \! = 57.1$$


$$K_d = K_p^* * T_d = 0.63$$

Problem 5.21

Gain margin of 45° means that when the magnitude plot crosses 0dB the phase must be -135° ($-180^{\circ}+45^{\circ}=-135^{\circ}$). A phase angle of -135° occurs at 1rad/s. With a gain of 1 the magnitude at 1rad/s is -20dB therefore the gain K must be 20dB to create a gain of 0dB at 1rad/s. A gain of 20dB means K=10. The book answer does not use straight line approximations and is therefore different. Straight line approximations are appropriate for these solutions.

	k (d	dB)	1/(10s+1)	1/(s+1)	total
w					
0.0	01	20	0.0	0	20
0	.01	20	0.0	0	20
	0.1	20	0.0	0	20
	1	20	-20.0	0	0
	10	20	-40.0	-20	-40
1	00	20	-60.0	-40	-80
10	000	20	-80.0	-60	-120


phase				
0.001	0	0.0	0	0
0.01	0	0.0	0	0
0.1	0	-45.0	0.0	-45
1	0	-90.0	-45.0	-135
10	0	-90.0	-90.0	-180
100	0	-90.0	-90.0	-180
1000	0	-90.0	-90.0	-180



Problem 5.22

mag (dB)	K = 1	10	1/(10s+1)	1/(s+1)	1/(0.1s+1)	total
w						
0.001	0	20	0.0	0	0	20
0.01	0	20	0.0	0	0	20
0.1	0	20	0.0	0	0	20
1	0	20	-20.0	0	0	0
10	0	20	-40.0	-20	0	-40
100	0	20	-60.0	-40	-20	-100
1000	0	20	-80.0	-60	-40	-160

phase (deg)	K = 1	10	1/(10s+1)	1/(s+1)	1/(0.1s+1)	total
w						
0.001	0	0	0.0	0	0	0
0.01	0	0	0.0	0	0	0
0.1	0	0	-45.0	0.0	0	-45
1	0	0	-90.0	-45.0	0.0	-135
10	0	0	-90.0	-90.0	-45.0	-225
100	0	0	-90.0	-90.0	-90.0	-270
1000	0	0	-90.0	-90.0	-90.0	-270



A: At 0dB the phase angle is -135° therefore phase margin = 180° - 135° = 45°

- If performed in MATLAB or other program, phase margin is 55.
- B: At -180° the gain is -20dB therefore the gain margin is +20dB

C: Instability occurs when gain or phase margin = 0 or are negative. If the gain margin is 20dB then a 20dB gain will yield a gain margin of 0 and cause instability.

Therefore K = 20dB = 10