

EMU

SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLUID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
1	EMU	OTHER	HWHS	KGP	KGP	HWH	TPKR1189	SUJOY KUMAR BISWAS	MMAN	04-06-2026	13:40			YS	CREW	108678	TPKR	38812	07-06-26 08:53	KGP	Y	DETAIL:SUN PROTECTOR OF WIND SCREEN IS TO BE PROVIDED ASAP	CLOSE_REM:as per EMU dept THE RAKE WILL BE ATTENDED ON ARRIVAL OF RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/06-06-2026 23:38-THE RAKE WILL BE ATTENDED ON ARRIVAL OF RAKE AT CARSHED AS SOON AS POSSIBLE	06-06-2026 23:38	04-06-2026 13:41
2	EMU	OTHER	HWHS	KGP	HWHS	KGP	TPKR1015	SANJAY BHUIYA	MMAN	07-06-2026	07:15			YS	CREW	198561	TPKR	38807	09-06-26 08:48	KGP	Y	DETAIL:CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:12-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	08-06-2026 23:12	07-06-2026 14:28
3	EMU	OTHER	HWHS	KGP	KGP	HWHS	TPKR1015	SANJAY BHUIYA	MMAN	07-06-2026	11:00			YS	CREW	108746	TPKR	38812	09-06-26 08:48	KGP	Y	DETAIL:CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:13-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	08-06-2026 23:13	07-06-2026 14:29
4	EMU	OTHER	HWHS	KGP	MCA	HWHS	TPKR1365	S.K.BAR	MMAN	08-06-2026	19:03	58	00	YS	CREW			38056	09-06-26 08:48	KGP	Y	DETAIL:ACP AT SEL 4TH FROM HWHEND.TM TRIED TO RE SET BUT UNSUCCESSFULL.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:13-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	08-06-2026 23:13	08-06-2026 19:16
5	EMU	BRAKE BINDING	HWHS	KGP	BVA	CGA	TPKR1322	SANJOY MANNA	MMAN	09-06-2026	08:03			YS	CREW				10-06-26 14:23	KGP	Y	DETAIL:MECHANICAL BRAKE BINDING BU6/DTC/248476 FOUND AT08.03HR,THEN REALESE AND TR STAT AT 09.30 HR	CLOSE_REM:AS PER EMU DEPT AFTER ARRIVAL OF THE RAKE AT CARSHED ON 09.06.26 , FOUND MARTENSITE ISSUE AT WHEEL NO 7 OF BU6 DTC. BOTH BRAKE BLOCK REPLACED	APP_REM:@KBBAR/10-06-2026 10:52-AFTER ARRIVAL OF THE RAKE AT CARSHED ON 09.06.26 , FOUND MARTENSITE ISSUE AT WHEEL NO 7 OF BU6 DTC. BOTH BRAKE BLOCK REPLACED	10-06-2026 10:52	09-06-2026 16:11
6	EMU	BRAKE BINDING	HWHS	KGP	MCA	KIG	TPKR1278	SUMAN CHOWDHURY	MMAN	10-06-2026	16:30	58	57	YS	CREW	198800	TPKR	38438	11-06-26 22:41	KGP	Y	DETAIL:UNIT 800 DTC BRAKE BINDING ,RELEASE AND ISOLATE ICA EPIC BIC BOTH.	CLOSE_REM:AS PER EMU DEPT ON 11.06.26 - FOUND RELATED WIRE OF EP BRAKE SHOWING EARTHED. SAME REPLACED	APP_REM:@KBBAR/11-06-2026 15:27-ON 11.06.26 - FOUND RELATED WIRE OF EP BRAKE SHOWING EARTHED. SAME REPLACED	11-06-2026 15:27	10-06-2026 18:43
7	EMU	OTHER	TPKR	KGP	KGP	TPKR	KGP1771	KAMALESH RAY	MMAN	11-06-2026	01:00			YS	CREW	198348	JAU	38830	11-06-26 22:41	KGP	Y	DETAIL:TR NO 38830 , U/NO-198351/350/349/348 , CAB AC NOT WORKING	CLOSE_REM:AS PER EMU DEPT CAB AC WILL BE ATTENDED AFTER ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/11-06-2026 15:30-CAB AC WILL BE ATTENDED AFTER ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	11-06-2026 15:30	11-06-2026 02:43
8	EMU	OTHER	TPKR	KGP	HWH	KGP	KGP0059	KARTIK SARKAR	Chief Loco Inspector	14-06-2026	05:46	0.1	116	YS	APPUSER	108693	TPKR	38703	15-06-26 22:59	KGP	Y	DETAIL:Unit No: 108693 (KGP End) Guard Side Seat Is Too Low.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/15-06-2026 22:56-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	15-06-2026 22:56	14-06-2026 05:48
9	EMU	OTHER	AMTA	KGP	HWHS	AMZ	TPKR1015	SANJAY BHUIYA	MMAN	14-06-2026	20:15			YS	CREW	248480	TPKR	38919	16-06-26 11:06	KGP	Y	DETAIL:BU-1 MAC ICON YELLOW& CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT AFTER FAULT RESET , MAC ICON BECAME NORMAL. REGARDING CAB AC SAME WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/16-06-2026 09:11-AFTER FAULT RESET , MAC ICON BECAME NORMAL. REGARDING CAB AC SAME WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	16-06-2026 09:11	14-06-2026 22:25
10	EMU	OTHER	TPKR	KGP	KGP	HWH	KGP0059	KARTIK SARKAR	Chief Loco Inspector	15-06-2026	08:31	116	0.1	YS	APPUSER	189278	TPKR	38810	16-06-26 11:06	KGP	Y	DETAIL:Unit No: 189278 HWH End Guard Side Look Glass To Be Change . Observe The Condition Of Look Out Glass In Picture.	CLOSE_REM:AS PER EMU WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/15-06-2026 22:59-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	15-06-2026 22:59	15-06-2026 08:36

SNO.	11	12	13	14	15	16
ABN.TYPE	EMU	EMU	EMU	EMU	EMU	EMU
SUBHEAD	CAB/AC NOT WORKING	OTHER	OTHER	OTHER	OTHER	OTHER
REPORTSTTN	BNDM	HWHS	SRC	TPKR	HWHS	BWN
REPORTDIV	KGP	KGP	KGP	KGP	KGP	KGP
FROM	CBSA	HWHS	HHW	KGP	PKU	HHW
TO	TATA	BCK	BCK	TPKR	HWHS	MSAE
CREW/CLUID	CKP0128	TPKR1363	SRC7239	KGP1771	TPKR1320	BWN1956
CREW/CLINAME	RAJNATH SINGH	BIBHAS BISWAS	SUNIL KUMAR SHAW	KAMALESH RAY	UTPAL DAN	S.C.MONDAL ELEC
DESIG	Chief Loco Inspector	MMAN	SGDP	MMAN	MMAN	MMAN
ABNDATE	17-06-2026	17-06-2026	17-06-2026	20-06-2026	21-06-2026	23-06-2026
ABN.TIME	08:57	11:30	12:46	07:00	03:45	16:10
FROMKM					70	00/1
TO KM					00	71/31
STATUS	YS	YS	YS	YS	YS	PN
FILLED BY	APPUSER	CREW	APPUSER	CREW	CREW	APPUSER
LOCO	238306	238881	238881	108678	10661	258001
LOCO SHED	KGPECS	TPKR	TPKR	TPKR	BTECS	KGPECS
TRAIN	68126	38501	38501	38708	38406	68121
SMSTO LP	19-06-26 18:48	18-06-26 21:13	18-06-26 21:13	21-06-26 10:44	21-06-26 22:34	
Div	KGP	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	Y	Y	N
Detail	DETAIL:AC of BU 238306 not working	DETAIL:U.NO-238881 AND U.NO-238884 BOTH CAB A/C NOT WORKING	DETAIL:Ac Not Working , In Both Cab. Tr No 38501 , Unit No 238881/82/83/84,	DETAIL:UNIT NO 678/677/676/675, TRAIN NO 38708 HORN SOMETIME NOT SOUNDING LOUDLY...	DETAIL:HHW END MOTORMAN SIDE CAB FAN NOT WORKING.	DETAIL:Unit number 258001/ TPKR /SER Tr No 68121 ,Talk Back not working UP and DN Both Directions ,Please do Needful action.
Closing Remarks	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED AT MEMU CARSHED/ KGP AFTER ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	CLOSE_REM:AS PER EMU DEPT BOTH THE CAB ACs ARE UNDER MEDHA s WARRANTY. THOSE WILL BE CHANGED IN PHASED MANNER.	CLOSE_REM:AS PER EMU DEPT BOTH THE CAB ACS ARE UNDER MEDHAS WARRANTY. THOSE WILL BE ATTENDED ON PHASED MANNER.	CLOSE_REM:AS PER EMU DEPT AT PKU NIGHT STABLING ON 21.06.26 - CHEKED AND FOUND OKAY	CLOSE_REM:as per EMU dept ATTENDED ON 21.06.26 and RECTIFIED.	
App Remarks	APP_REM:@KBBAR/19-06-2026 18:00-WILL BE ATTENDED AT MEMU CARSHED/ KGP AFTER ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/18-06-2026 10:42-BOTH THE CAB ACs ARE UNDER MEDHA' s WARRANTY. THOSE WILL BE CHANGED IN PHASED MANNER.	APP_REM:@KBBAR/18-06-2026 10:46-BOTH THE CAB ACS ARE UNDER MEDHAS WARRANTY. THOSE WILL BE ATTENDED ON PHASED MANNER.	APP_REM:@KBBAR/21-06-2026 06:58-AT PKU NIGHT STABLING ON 21.06.26 - CHEKED AND FOUND OKAY	APP_REM:@KBBAR/21-06-2026 17:13- ATTENDED ON 21.06.26	
App Remarks Date	19-06-2026 18:00	18-06-2026 10:42	18-06-2026 10:46	21-06-2026 06:58	21-06-2026 17:13	
Reporting Date	17-06-2026 08:59	17-06-2026 18:44	17-06-2026 18:48	20-06-2026 11:11	21-06-2026 06:30	23-06-2026 19:39