```
#-----
# Servo demonstration
#----
import RPi.GPIO as GPIO
from time import sleep
# Servo pin
SERVO PIN = 18
# Use BroadComm pin numbers
GPIO.setmode(GPIO.BCM)
# Setup the servo
GPIO.setup(SERVO PIN,GPIO.OUT)
pwm = GPIO.PWM(SERVO_PIN, 50)
pwm.start(6.5)
sleep(1)
pwm.ChangeDutyCycle(0)
try:
   while True:
        duty cycle = input('Enter Duty Cycle: ')
       duty_cycle = float(duty_cycle)
       pwm.ChangeDutyCycle(duty_cycle)
       sleep(0.5)
       pwm.ChangeDutyCycle(0)
finally:
    GPIO.cleanup()
```