Print Name: KEY

MSE 2001H Quiz 5 November 11, 2011

The T-T-T diagram for the isothermal transformation of a eutectoid carbon steel is shown below.

Draw a heat treatment (a <u>line</u> beginning at the starting point) that will produce a microstructure consisting of 50% fine pearlite and 50% martensite.

